

PRODUCT CHANGE NOTIFICATION

PCN#: COPPER, OUTLETS, SURFACE RACEWAY

20191125

ISSUE DATE: 11/5/2019

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Not Required for discontinuation)

The tolerance for the LD raceway line will be changing from +/- .090in to +/- .130in. This is to correct an issue from original documentation to align our specifications on all raceway products. Currently all raceway and duct have this tolerance except for LD and we are simply updating the specifications. The fittings offered in this LD line have enough tolerance to account for this small change to the raceway and we do not foresee this resulting in improper installation issues. New drawings will be updated on the website.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*	2020	2	14

***Important:** A return material authorization (RMA) may be obtained for the affected part numbers listed above if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's 1/1/19 Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(s)
LD10EI6-A
LD10EI8-A
LD10IG10-A
LD10IG6-A
LD10IG8-A
LD10IW10-A
LD10IW6-A
LD10IW8-A
LD10WH10-A
LD10WH6-A
LD10WH8-A
LD3EI10-A
LD3EI6-A
LD3EI8-A
LD3IG10-A
LD3IG6-A
LD3IG8-A
LD3IW10-A
LD3IW6-A
LD3IW8-A
LD3WH10-A
LD3WH6-A
LD3WH8-A
LD5BL6-A
LD5EI10-A
LD5EI6-A
LD5EI8-A
LD5IG10-A
LD5IG6-A
LD5IG8-A
LD5IW10-A
LD5IW6-A
LD5IW8-A
LD5WH10-A
LD5WH6-A
LD5WH8-A