

PRODUCT CHANGE NOTIFICATION

Product Category RACKS 20221207-1

Product Group ROAR

ISSUE DATE: 7-Dec-22

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

Please note B4P generation is being discontinued and will be transitioning to the C4P generation. B4P parts will not be compatible with C4P parts and C4P parts will not be compatible with B4P parts.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*	2023	1	1

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(s)	Replacement Part 1	Discontinuation
		Date
B4PCACWH/N	NO-REPLACEMENT	1-Jan-23
PR2B4PCAC96WH/N	NO-REPLACEMENT	1-Jan-23
PR2B4P3679EP2WH	NO-REPLACEMENT	1-Jan-23
PR2B4P3696EP2WH	NO-REPLACEMENT	1-Jan-23
PR2V1036ATWH/N	NO-REPLACEMENT	1-Jan-23
B4P3679WH	NO-REPLACEMENT	1-Jan-23
B4P3696WH	NO-REPLACEMENT	1-Jan-23
B4P36ACTPWH/N	NO-REPLACEMENT	1-Jan-23
B4P36AEPWH/N	NO-REPLACEMENT	1-Jan-23
PRVF10ACKWH/N	NO-REPLACEMENT	1-Jan-23
PRV1036ATWH/N	NO-REPLACEMENT	1-Jan-23
PRVF1296ACKWH/N	NO-REPLACEMENT	1-Jan-23
PR2V06CACWH/N	NO-REPLACEMENT	1-Jan-23
PR2V0636ATWH/N	NO-REPLACEMENT	1-Jan-23
PR2V1236ATWH/N	NO-REPLACEMENT	1-Jan-23
B4P3696AEPWH/N	NO-REPLACEMENT	1-Jan-23
B4P36WH	NO-REPLACEMENT	1-Jan-23
PR2V10CACWH/N	NO-REPLACEMENT	1-Jan-23
PRV6ACKWH/N	NO-REPLACEMENT	1-Jan-23