


May, 2009

Discontinuation of DS4E Relay (4 Form C)



Panasonic Electric Works announces the discontinuation of DS4E relays.

1. Reason: Decrease in market demand

2. Affected parts:

Nominal coil voltage	Standard type		High sensitivity type	
	Single side stable type	2 coil latching type	Single side stable type	2 coil latching type
	Part No.	Part No.	Part No.	Part No.
1.5V DC	DS4E-M-DC1.5V	DS4E-ML2-DC1.5V	DS4E-S-DC1.5V	DS4E-SL2-DC1.5V
3V DC	DS4E-M-DC3V	DS4E-ML2-DC3V	DS4E-S-DC3V	DS4E-SL2-DC3V
5V DC	DS4E-M-DC5V	DS4E-ML2-DC5V	DS4E-S-DC5V	DS4E-SL2-DC5V
6V DC	DS4E-M-DC6V	DS4E-ML2-DC6V	DS4E-S-DC6V	DS4E-SL2-DC6V
9V DC	DS4E-M-DC9V	DS4E-ML2-DC9V	DS4E-S-DC9V	DS4E-SL2-DC9V
12V DC	DS4E-M-DC12V	DS4E-ML2-DC12V	DS4E-S-DC12V	DS4E-SL2-DC12V
24V DC	DS4E-M-DC24V	DS4E-ML2-DC24V	DS4E-S-DC24V	DS4E-SL2-DC24V
48V DC	DS4E-M-DC48V	DS4E-ML2-DC48V	DS4E-S-DC48V	DS4E-SL2-DC48V

*We are discontinuing also the 1 coil latching type and reverse polarity type (add suffix-R).

3. Last time buy: End of October 2009. Please note lead time through end of production is 16-20 weeks.

4. Substitution: DS2E relay (2 Form C) - 2 pieces

**Panasonic Electric Works
Corporation of America**

- Head Office: 629 Central avenue, New Providence, NJ 07974
- Telephone: (908) 464-3550
- Fax: (908) 464-5719