



PRODUCT OBSOLESCENCE MEMO

GAS DISCHARGE TUBES



Bourns® Model 2027-xx-B19xx 2-Pole Gas Discharge Tube to be Discontinued

Riverside, California – October 8, 2019 – Bourns is discontinuing the [Model 2027-xx-B19xx](#) 2-Pole Gas Discharge Tube. A lack of sales volume and diminishing demand necessitates this action.

A list of obsolete part numbers and recommended replacement products available for your consideration and testing is shown below and on page 2. Please contact the [Bourns team of Field Application Engineers](#) if you have any questions regarding the suggested replacement parts and your application requirements.

Please plan for the following deadlines:

Last time buy date: **April 8, 2020**

Last time ship date: **October 8, 2020**

Should you have any questions or need additional information, please feel free to contact [Customer Service/Inside Sales](#).

Obsolete Part Numbers	Suggested Replacement Part Numbers	Comments
2027-07-B19 2027-07-B19LF	2027-07-B10 2027-07-B10LF	2027-XX-B10 has shorter lead length, bent lead tip end
2027-09-B19 2027-09-B19LF	2027-09-B10 2027-09-B10LF	
2027-15-B19 2027-15-B19LF	2027-15-B10 2027-15-B10LF	
2027-20-B19 2027-20-B19LF	2027-20-B10 2027-20-B10LF	
2027-23-B19 2027-23-B19LF	2027-23-B10 2027-23-B10LF	
2027-25-B19 2027-25-B19LF	2027-25-B10 2027-25-B10LF	

Continued on next page

GDT1919



Obsolete Part Numbers	Suggested Replacement Part Numbers	Comments
2027-30-B19 2027-30-B19LF	2027-30-B10 2027-30-B10LF	2027-XX-B10 has shorter lead length, bent lead tip end
2027-35-B19 2027-35-B19LF	2027-35-B10 2027-35-B10LF	
2027-40-B19 2027-40-B19LF	2027-40-B10 2027-40-B10LF	
2027-42-B19 2027-42-B19LF	2027-42-B10 2027-42-B10LF	
2027-47-B19 2027-47-B19LF	2027-47-B10 2027-47-B10LF	
2027-60-B19 2027-60-B19LF	2027-60-B10 2027-60-B10LF	