

1 Products affected

| Product hierarchy no. * | | | | Part no. | SBU | Type / Description | Customer part no. |
|-------------------------|-----|-----|------------|-----------|--------------------|--------------------|-------------------|
| SBU | PG | PGU | Type | | | | |
| 01 | 002 | 012 | 0000000529 | 0031.3571 | Circuit protection | Fuse holder FAU | |
| | | | | 0031.3572 | | | |
| | | | | 0031.3573 | | | |
| | | | | 0031.3577 | | | |
| | | | | 0031.3581 | | | |
| | | | | 0031.3583 | | | |
| | | | | 0031.3584 | | | |

*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

2 Type of change

The inscription at the socket of the fuse holder changes. SEV and SEMKO symbol are no longer on the socket.

3 Detailed description of change

The inscription changes as follows:

| Old inscription | New inscription |
|-----------------|-----------------|
| | |

4 Reason of change

Because of the harmonizing of the European fuse holder standards, SEMKO and SEV symbols are removed from the fuse holder socket. The fuse holder FAU is approved acc. to IEC 60127-6 at VDE.

5 Release date

The change comes into effect on ww 16/2015 (date code 1516 or higher on packaging label).

6 Impact of change and recommended action

| | |
|------------------|------------------------------------|
| Form: | Yes (inscription approval symbols) |
| Fit: | No |
| Function: | No |
| Production Site: | No |
| Product Label: | No |

7 Reference Documents / Attachments

| Kind of document | Remarks |
|--------------------------|---|
| Data sheet FAU | Web link data sheet FAU |
| VDE approval acc. to IEC | Web link approval FAU |

| FAU | | | | | 0118.2255 | |
|---------------|------------|--------------|-------------|------------------|-----------|--------|
| creation date | created by | release date | released by | notification no. | revision | page |
| 2015-01-13 | dislercy | 2015-01-16 | dislercy | | | 1 of 1 |