


PCN Number	501462	Date Issued	December 11, 2017
Reason for Change	Change to Product		
Change Type Description	This letter is to inform you that changes are being made to the part(s) identified in this Notice. The change may affect the fit, form, function or appearance of the parts, or it may result in a change to the specification. The pictures below show an example of the possible differences.		
Assessment of Change	Passed FAI		
Internal Molex Qualification Date	January 25, 2017		
Sample Availability Date (Changed Part)	January 25, 2017		
Planned Implementation Date	February 25, 2017		
Method of Identifying Change	Date code		

RELEASED

Before

- Housing material of 48099 Series as Nylon 46



Overview of after change

- Current 48099 Series use Nylon 46 resin, due to this material has high hygroscopic feature which lead to risk of blistering while IR reflow. We propose to change the raw material of the product (from Nylon 46 change to LCP), it will benefit stock both at Molex & Customer side, no function impact on customer application.
- Product Impact
 - No appearance change on product,
 - Avoid risk of blistering while IR reflow
- Part Number Impact
 - 480994000/ 480995701
- Qualification report and samples available upon request

Molex Part #

480994000

480995701