

Title of Change:	Update to PD23900Z - Product Discontinuance for Niigata parts products with extended last ship date
Last Time Buy Date:	05 Jul 2021
Last Ship Date:	31 Dec 2022
Contact information:	Contact your local onsemi Sales Office or Noriaki.Sakamoto@onsemi.com
Type of notification:	Customers must notify onsemi (< PCN.Support@onsemi.com >) in writing within 90 days of receipt of this notification if they consider the discontinued product to be "Sole Source." onsemi and the customer may negotiate an appropriate End-of-Life.

Description and Purpose:

onsemi is publishing this document to notify the extended last ship date for product listed in this notice.

onsemi wishes to promptly inform our customer of our intent to exit this small portion of our overall portfolio so that you may plan appropriately and effectively for replacement devices.

For those devices that have no recommended replacement identified, onsemi has partnered with Rochester Electronics and Flip Electronics who will carry any remaining device inventory to potentially allow for a continued source after onsemi has completed its business process

PLEASE NOTE: onsemi may implement minimum order quantities or dollar amounts based on inventories available. Also, Devices on this Product Discontinuance become NCNR (Non-Cancelable, Non-Returnable).

For questions or concerns regarding this notification, please contact your local sales office or customer service representative.

Additional contacts are:

Americas:

Tom Siegel (tom.siegel@onsemi.com)
 ☎ +1 765 868 5022
 USA

Europe:

Andrej Tomasik (andrej.tomasik@onsemi.com)
 ☎ +421 33790 2229
 Slovakia

Japan:

Isao Usuki (isao.usuki@onsemi.com)
 ☎ +81 3 6880 1771
 Japan

Asia Pacific:

Stephen Ng (stephen.ng@onsemi.com)
 ☎ +852 2689 0209
 China

List of Affected Parts:

Note: Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the [PCN Customized Portal](#).

Device to be Discontinued	Replacement part	Supplier
STK5Q4U352J-E	#NONE	#NA
STK5Q4U362J-E	#NONE	#NA
STK551U3A2A-E	#NONE	#NA
STK554U362C-E	#NONE	#NA
STK554U392C-E	#NONE	#NA
STK57FU394AG-E	#NONE	#NA
STK672-440BN-E	#NONE	#NA
STK681-360-E	#NONE	#NA

STK682-010-E	#NONE	#NA
STK681-332-E	#NONE	#NA
STK672-732AN-E	#NONE	#NA
STK672-642AN-E	#NONE	#NA
STK672-632AN-E	#NONE	#NA
STK672-442BN-E	#NONE	#NA
STK672-442AN-E	#NONE	#NA
STK672-432BN-E	#NONE	#NA
STK672-432AN-E	#NONE	#NA
STK672-740AN-E	#NONE	#NA
STK672-640CN-E	#NONE	#NA
STK672-640AN-E	#NONE	#NA
STK672-630CN-E	#NONE	#NA
STK672-630AN-E	#NONE	#NA

Appendix A: Changed Products

PCN#: PD23900Z9
Issue Date: Jun 13, 2022

Product	Customer Part Number	Qualification Vehicle	New Part Number	Replacement Supplier
STK5Q4U352J-E				
STK5Q4U362J-E				
STK551U3A2A-E				
STK57FU394AG-E				
STK672-430AN-E				
STK672-440AN-E				
STK672-440BN-E				
STK681-360-E				
STK682-010-E				
STK681-332-E				
STK672-732AN-E				
STK672-632AN-E				
STK672-442BN-E				
STK672-442AN-E				
STK672-432BN-E				
STK672-432AN-E				
STK672-740AN-E				
STK672-640AN-E				
STK672-630CN-E				
STK672-630AN-E				
STK554U392C-E				