



EFFECTIVE IMMEDIATELY

September 10, 2021

Dear Fluke Distributor:

The following distribution Product is being phased out effective immediately. This letter is your notification of our product change.

PLEASE INFORM ALL RELEVANT PERSONNEL WITHIN YOUR ORGANIZATION.

Product Family	Obsolete Item Number	Obsolete Model	Suggested Replacement Item	Suggested Replacement Model
FIBER	4116318	MMC-50-SCLC	5235139	MMC-50-SCLC-M
FIBER	4116365	MMC-62-SCLC	5235142	MMC-62-SCLC-M
FIBER	4496857	MMC-50-LCLC	5235156	MMC-50-LCLC-M
FIBER	4496869	MMC-62.5-LCLC	5235163	MMC-62.5-LCLC-M
FIBER	4116408	SMC-9-SCLC	5235174	SMC-9-SCLC-M
FIBER	4139294	SMC-9-SCLCAPC	5235188	SMC-9-SCLCAPC-M
FIBER	4496878	SMC-9-LCLC	5235195	SMC-9-LCLC-M
FIBER	4953023	SMC-9-SCAPC/LCAPC	5235206	SMC-9-SCAPC/LCAPCM
FIBER	4953050	SMC-9-LCAPC/LCAPC	5235214	SMC-9-LCAPC/LCAPCM
FIBER	4496979	MRC-50-LCLC-0.3M	5235371	MRC-50-LCLC-0.3M-M
FIBER	4496993	SRC-9-LCLC-0.3M	5235398	SRC-9-LCLC-0.3M-M
FIBER	4953136	SRC-9-SCAPC/LCAPC	5235405	SRC-9-SCAPC/LCAPCM
FIBER	4953172	SRC9SCAPCLCAPC0.3M	5235410	SRC9SCAPCLCAPC.3MM
FIBER	4953185	SRC-9-SCLC-0.3M	5235422	SRC-9-SCLC-0.3M-M
FIBER	4320193	MRC-50-EFC-SCLC	5235431	MRC-50-EFC-SCLC-M
FIBER	4320262	MRC-50EFC-SCLCKIT	5235454	MRC-50EFC-SCLCKITM
FIBER	4320237	MRC-625-EFC-SCLC	5235468	MRC-62EFC-SCLCKITM

FIBER	4322632	MRC-50-LCLC	5235479	MRC-50-LCLC-M
FIBER	4322671	MRC-625-LCLC	5235487	MRC-625-LCLC-M
FIBER	4335564	SRC-9-SCLC-KIT	5235493	SRC-9-SCLC-KIT-M
FIBER	4335629	SRC-9-SCLCAPCKIT	5235507	SRC-9-SCLCAPCKIT-M
FIBER	4364126	SRC-9-LCLC	5235529	SRC-9-LCLC-M
FIBER	4774936	SRC-9-LCLCAPC	5235541	SRC-9-LCLCAPC-M

Should you have any questions regarding this notice, please contact your Fluke Sales Manager.

Kind regards,
 Zak Bollenbacher
 Director of Commercial Strategy