

IIoT Product Change Notice



The change will be applied on the ULI-234TCI (BB-485OPDRI). If you need more information or special support, please contact the corresponding PMs/AEs listed in the table below.





Note: The ordering process has not been changed. Customers should continue to order model number BB-485OPDRI

- Reason for the Change:** Branding and UL File change.
- Affected Products:** ULI-234TCI (BB-485OPDRI)
- Impact on Application:** No change to form, fit, or function.

Item	Impact
Impact on Mechanical Design	No
Impact on Software Compatibility	No
Impact on Environment Characteristics	No
Impact on System Certifications	Yes – UL file is changing from E245458 to E327848
Physical Outlook Change	Yes
Ordering P/N Change	No
Cut-in Implement	Component Running Change

4. Description of the Change(s):

Affected Models	Current Component	New Component	Category	Outlook Difference	Reason
ULI-234TCI BB-485OPDRI	20BB250-10539-00	1990038124T010	Label	<p>Old name plate</p>  <p>New name plate</p> 	Branding

<p>ULI-234TCI BB-485OPDRI</p>	<p>20BB9319</p>	<p>20BB9319R1</p>	<p>Label</p>	<p>Old Name Plate</p> <p>This device complies with Part 15 of the FCC rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any that may cause undesired operation.</p>   <p>WARNING - Explosion Hazard - Do Not Disconnect While Circuit Is Live Unless Area is Known To Be Non-Hazardous.</p> <p>New Name Plate</p> <p>This device complies with Part 15 of the FCC rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any that may cause undesired operation.</p>   <p>WARNING - Explosion Hazard - Do Not Disconnect While Circuit Is Live Unless Area is Known To Be Non-Hazardous.</p>	<p>Branding</p>
-----------------------------------	-----------------	-------------------	--------------	---	-----------------

5. Implementation & Schedule of the Change(s):

Affected Models	ECOM Number	Estimated Effective Date	Cut-in Implement	Change Description
ULI-234TCI (BB-485OPDRI)	ECOM-196349	12/30/2022	Running Change	Update name plate, UL file change.

*Note: Cut-in progress depends on factory production schedule.

** Note: The ordering process has not been changed. Customers should continue to order model number BB- 485OPDRI

Contact Windows

PM	Brian Foster / brian.foster@advantech.com
AE	N/A