

PCN Number:	20170614000	PCN Date:	June 27, 2017
Title:	Datasheet for DAC081C081, DAC081C085		
Customer Contact:	PCN Manager	Dept:	Quality Services
Change Type:			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Design
<input type="checkbox"/>	Assembly Process	<input checked="" type="checkbox"/>	Data Sheet
<input type="checkbox"/>	Assembly Materials	<input type="checkbox"/>	Part number change
<input type="checkbox"/>	Mechanical Specification	<input type="checkbox"/>	Test Site
<input type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Material
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Materials
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Process

Notification Details

Description of Change:

Texas Instruments Incorporated is announcing an information only notification. The product datasheet(s) is being updated as summarized below. The following change history provides further details.



DAC081C081, DAC081C085

SNAS449F – FEBRUARY 2008 – REVISED MAY 2017

Changes from Revision E (January 2016) to Revision F

Page

- | | |
|---------------------------------|----|
| • Added column to Table 1. | 21 |
|---------------------------------|----|

The datasheet number will be changing.

Device Family	Change From:	Change To:
DAC081C081, DAC081C085	SNAS449E	SNAS449F

These changes may be reviewed at the datasheet links provided.

<http://www.ti.com/product/DAC081C081>

Reason for Change:

To accurately reflect device characteristics.

Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.

Changes to product identification resulting from this PCN:

None.

Product Affected:

DAC081C081CIMK/NOPB	DAC081C081CIMKX/NOPB	DAC081C081CISD/NOPB	DAC081C081CISDX/NOPB
DAC081C085CIMM/NOPB	DAC081C085CIMMX/NOPB		

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com