

## Global Change Notification (GCN)

Product Family	Impact OD	10635866
		GCN Number
Series	Multiple	May 19, 2014
		Date Issued
Reason For Change	Manufacturing Process Change	
Change Description	This letter is to inform you of a process change for Impact OD. We will utilize mate-side (single side plating only) on signal and ground terminals for the following series: 171570, 171572, 171573, 171574, 171575, 171576, 171788.	
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.	
Reason For Short Notice Exception	Special Request	
Assessment Of Change (How Product Will Be Qualified & Validated)	Test report is available upon request.	
Internal Molex Qualification Date (Planned Date Information Available)	May 09, 2014	
Sample Availability Date (Changed Part)	May 09, 2014	
Date of Implementation	May 20, 2014	
Method of Identifying Change	Visual difference in plating appearance	
Recommended Replacement Parts	N/A	
Last Time Buy Date for Obsolete Parts		
Last Time Ship Date for Obsolete Parts		

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	QuiNann Lim	QuiNann.Lim@molex.com	+31-40-295-8472
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

**Molex, Inc.**  
 2222 Wellington Court  
 Lisle, IL 60532  
 TEL: 630-969-4747  
[www.molex.com](http://www.molex.com)