



Product Discontinuation Notice: DS2 Series Relays

PDN.PG0001.3.15.2021

3.15.2021

Effective Date:	March 26, 2021
Last Time Buy Date:	September 28, 2021
Last Eligible Ship Date:	December 31, 2021
Discontinuation Details:	The DS2 Series Relays are being discontinued due to low market demand.
Suggested Replacement:	There are no direct replacements. Please consider the TX Series Relays as an alternate with similar specifications but different footprint.
Affected Part Numbers:	See Attached.
Datasheets:	See Attached.
Notes:	DS1 Series Relays are not included in this Product Notice and remain active.

Affected Part Numbers	Suggested Replacement Part Numbers
DS2E-S-DC3V	TX2-3V
DS2E-S-DC5V	TX2-5V
DS2E-S-DC6V	TX2-6V
DS2E-S-DC9V	TX2-9V
DS2E-S-DC12V	TX2-12V
DS2E-S-DC24V	TX2-24V
DS2E-S-DC48V	-
DS2E-SL2-DC3V	TX2-LT-3V
DS2E-SL2-DC5V	TX2-LT-5V
DS2E-SL2-DC6V	TX2-LT-6V
DS2E-SL2-DC9V	TX2-LT-9V
DS2E-SL2-DC12V	TX2-LT-12V
DS2E-SL2-DC24V	TX2-LT-24V
DS2E-SL2-DC48V	-
DS2Y-S-DC1.5V	-
DS2Y-S-DC3V	TX2-3V
DS2Y-S-DC5V	TX2-5V
DS2Y-S-DC6V	TX2-6V
DS2Y-S-DC9V	TX2-9V
DS2Y-S-DC12V	TX2-12V
DS2Y-S-DC24V	TX2-24V
DS2Y-S-DC24V-H350	TX2-24V
DS2Y-S-DC48V	-

Affected Series Affected Part Number

DS2	DS2Y-S-DC24V-TB
DS2	DS2Y-S-DC48V-TB
DS2	DS2Y-S-DC12V-TB
DS2	DS2E-S-DC9V-TB
DS2	DS2E-S-DC24V-TB
DS2	DS2E-S-DC6V-TB