

# TAIYO YUDEN

Taiyo Yuden (U.S.A.), Inc.  
10 N. Martingale Road, Ste 575  
Schaumburg, IL 60173  
Tel (847) 925-0888 Fax (847) 925-0899  
<http://www.t-yuden.com>

---

---

## DISCONTINUATION NOTICE

---

---

DATE: April 4, 2013

RE: Discontinuation of  
1) Leaded Normal Mode Choke Coils  
2) Radial Leaded Inductors  
3) Multilayer Chip Varistors

REF NO.: UTY-DN13-02D

Taiyo Yuden (U.S.A.) Inc. hereby gives notice that the following part numbers will be discontinued effective immediately. There is no sales history on those parts and therefore no last orders will be accepted.

Discontinued Parts Leaded Normal Mode Choke Coils	Discontinued Parts Radial Leaded Inductors	Discontinued Parts Multilayer Chip Varistors
FL05RD100AT	LHL16NB101K	VR1005AAA080-T
FL05RD100AZ	LHL16NB102J	VR1005AAA120-T
FL05RD1R0E	LHL16NB103J	VR1005AAA180-T
FL05RD1R0ET	LHL16NB151K	VR1005AAA270-T
FL05RD1R0EZ	LHL16NB152J	VR1005BBA080-T
FL05RD200A	LHL16NB221K	VR1005BBA270-T
FL05RD200AT	LHL16NB222J	VR1005CCA270-T
FL06BT04	LHL16NB331K	
	LHL16NB332J	
	LHL16NB470K	
	LHL16NB471K	
	LHL16NB472J	
	LHL16NB680K	
	LHL16NB681K	
	LHL16NB682J	
	LHL16TB101K	
	LHL16TB102J	
	LHL16TB103J	
	LHL16TB151K	
	LHL16TB152J	
	LHL16TB221K	
	LHL16TB222J	
	LHL16TB331K	
	LHL16TB332J	
	LHL16TB470K	
	LHL16TB471K	
	LHL16TB472J	
	LHL16TB680K	
	LHL16TB681K	
	LHL16TB682J	

The information in this notice is applicable only to taiyo Yuden customers in North and South America. Discontinuation schedules and availability may vary in other regions. Please contact the Taiyo Yuden sales office responsible for sales in your country for details on this notice.

Issued by TAIYO YUDEN (U.S.A.) INC.  
Sales Planning Department