



Phoenix Contact Inc.
P.O. BOX 4100
Harrisburg, PA 17111-0100
Phone: 717-944-1300

Product Discontinuation

PDN-ICC-7992-2022

Business Unit	Product Line Code	Type of Change	Action	Date of Issue
ICC - Industrial Cabinet	BE2	Product Discontinuation	Notify Distributors and Field	6/7/2022

Phoenix Contact's factory has announced the following product(s) is going to be discontinued. Existing specifications will be met or exceeded. Technical support of the discontinued product will continue, as required. Please review and acknowledge this document and take the appropriate action with respect to your existing inventory and ordering replacement parts.

Description for Product Discontinuation

Due to lack of sales and technical improvements, the FBSW wire bridges are being discontinued. Standard FBS bridges may be used in their place.

Stock Status

Can existing stock still be used?	Yes
Is mixture of stock acceptable?	Yes

Transaction Dates

Last Buy from Phoenix Contact:	7/31/2022
Last Scheduled Ship from Phoenix Contact:	8/31/2022

Should you have any issues with the timeline or content of this product discontinuation, please contact Phoenix Contact using the information below. Customers should acknowledge receipt of the PDN within 30 days of delivery of the PDN; provided, however, that the failure to acknowledge receipt does not affect the product discontinuation or the effective date thereof.

Contact Info:

Cory Myer
cmyer@phoenixcontact.com

Thank you,

Alan Sappe

Sr. Manager - Shop Floor Productivity & Smart Engineering



Phoenix Contact Inc.
P.O. BOX 4100
Harrisburg, PA 17111-0100
Phone: 717-944-1300

Product Discontinuation

Discontinued Part #	Type Description	Replacement Part #	Type Description
3030170	FBSW 2-5/60MM		
3030171	FBSW 2-5/110MM		
3030172	FBSW 2-5/250MM		