

**Product Change Notification** 

520 Park East Blvd., New Albany, IN 47150 U.S.A (812)-944-6733 / 1-800-SAMTEC9

1. ECN #: 272753

2. Date of Announcement: May 31, 2016

### 3. Series:

• HDMR - HDMR FLANGED SURFACE MOUNT SOCKET

### 4. Part #'s Affected


• HDMR-19-XX-X-SM-XX-XX


## 5. Description of Change:

Change assembly method from manual assembly to insert molding process.

### 6. Method of Identifying Change

Insert molding process assemblies have minor visual difference compared to the manually assembled product. Remove protrusions on shield;





## 7. Reason for Change:

Insert molding process improves manufacturability when compared to the manual assembly process.

## 8. Impact of Change on Form, Fit, or Function:

• Form - housing and shields have minor cosmetic differences.

# 9. Projected Implementation Date: June 18, 2016