

## 1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type				
02	007	013	0000002297	See list below	Connectors	4797 Appliance Outlet 16A 70°	

\*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

List of part numbers affected							
4797.0020							



The part numbers 4797.3000 and 4797.3025 are not part of this change. The change for said two part numbers will be executed at a later stage.

Details for already changed 4797 part number can be found in PCN D10-034-720. (PCN - 4797 Cord Retention Notches Added)

## 2 Type of change

Two laterally positioned notches added to the molding body.

## 3 Detailed description of change

Old product appearance	New product appearance
	

## 4 Reason of change

The notches are implemented as a standard feature to be compatible with side latching cord retention systems such as P-Lock, SecureLock or TwyLock.

## 5 Release date

The change takes effect in production in ww21/2020 (Production date code 2021 or higher on label). The validity of the approval certificates is not affected by this change.

## 6 Impact of change and recommended action

Form	Yes	Laterally positioned notches. Fully backwards compatible
Fit	No	-
Function	Yes	Compatibility with side latching cord retention systems
Manufacturing	No	-
Label	No	-
Packaging	No	-

## 7 Reference Documents / Attachments

Kind of document	Remarks
<a href="#">4797 - Data Sheet</a>	
<a href="#">4797 - PCN - D10-034-720</a>	PCN for already changed 4797 products

Product Change Notification					PCN - 4797 Cord Retention Notches Added - Part		
owner	creation date	release date	released by	change order no	rev	page	
vetersa	04.03.2020	13.05.2020	muehlema	2019486	A	1 of 1	D10-043-493