

June 29, 2022  
Issue Number: 1026

**Discontinuation Notice 3M™ Textool™ OEM LCC Sockets**

To Our 3M Authorized Distributors:

3M will be obsoleting 3M™ Textool™ OEM LCC Sockets immediately. This will impact all products on drawing number TS-0359. List of 3M part numbers, 3M skus, and SAP ID's below.

Lead Count	Part Number	SKU	SAP ID
32	232-1271-00-1102JH	JE150379186	7010404247
68	268-5401-00-1102JH	JE150379194	7000090420
	268-5401-11-1102JH	JE150901401	7000007718
	268-5401-00-0000	-	-
	268-5401-50-0000	JE150085726	-
	268-5401-50-1102JH	JE150379202	7010404248
	268-5401-51-1102JH	JE150177192	-
	268-5401-51-0000	-	-
	268-5401-52-0000	JE150085718	7010404000
	268-5401-52-1102JH	JE150177200	-
84	284-1273-00-1102JH	JE150379210 / JE150181475	-
	284-1273-05-1102JH	JE150379228 / JE150181483	-

**What actions and impact will this have on purchase orders?**

Due to the fact that 3M cannot obtain materials to build the 3M Textool OEM LCC sockets, we will not be able to offer a last time buy. There are no 3M replacement parts for these sockets.

If you have questions related to this notice, please contact your 3M Sales Representative or Customer Service Representative who will be pleased to help you.

Thank you for your understanding and continued partnership with 3M.

Sincerely,

Brent Gossett  
Channel Operations  
3M Interconnect Products