

## 1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PGU	Type				
02	007	012	0000002288	See list below	Connectors	4788	

\*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)


List of part numbers affected				
4788.3000	4788.3100	4788.3200	4788.4000	4788.4100
4788.5000	4788.5100	4788.6000	4788.6100	4788.7000
4788.7100	4788.7200	4788.8000	4788.8100	

## 2 Type of change

Each product marked with individual part number.

## 3 Detailed description of change

Place of marking on product.



## 4 Reason of change

Part number on product for identification and administrative reasons.

## 5 Release date

The change will be rolled-out individually by all part numbers affected starting ww 01/2014 and last approx. 6 months.

## 6 Impact of change and recommended action

Form: N/A  
Fit: N/A  
Function: N/A  
Production Site: N/A  
Product Label: Part number on product

## 7 Reference Documents / Attachments

Kind of document	Document number	Remarks
<a href="#">Data sheet 4788</a>		

4788					0118.2185	
creation date	created by	release date	released by	notification no.	revision	page
2013-09-25	hermanur	2013-11-26	hermanur	25254	-	1 of 1