

To: _____

Product Change Notification

Type of Notification: Removal of internal potentiometer

This is to advise you that the following products have been changed.

1. Product Being Changed (All part numbers that start with following)

LHA150F-□, LHA300F-□





2. Description of Change

The internal potentiometer (VR201) will be removed to prevent mishandling when user adjusts output voltage.

The VR201 is used for adjusting current characteristics internally and user does not need to adjust. Tab 2.1 shows the difference of appearance between "existing" and "after change".

This change does not affect electronic or mechanical specifications, nor does it affect safety standards compliance.

Tab 2.1 The Appearance Difference between "Existing" and "After Change"

No.	model	Existing	After Change
1	LHA150F	 <div style="border: 1px solid red; padding: 2px; width: fit-content; margin: 5px auto;">VR201 (potentiometer for adjusting current)</div>	 <div style="border: 1px solid red; padding: 2px; width: fit-content; margin: 5px auto;">Removed</div>
2	LHA300F	 <div style="border: 1px solid red; padding: 2px; width: fit-content; margin: 5px auto;">VR201 (potentiometer for adjusting current)</div>	 <div style="border: 1px solid red; padding: 2px; width: fit-content; margin: 5px auto;">Removed</div>

3. PCN Effective Date

This a running change, beginning with production in early September 2020.

Please be advised that the schedule may be changed without prior notice due to stock availability.

4. Who to Contact at Cosel with Questions

Cosel sales representatives.

Should there be any questions, please feel free to contact us.

Sincerely yours,



Yoshimichi Hirokawa
 General Manager
 US Design Dept.
 Cosel Co., Ltd.