

PRODUCT CHANGE NOTIFICATION

Product Category COPPER CONNECTORS 20220915-2

Product Group ENTERPRISE CONNECTIVITY

ISSUE DATE: 15-Sep-22

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

A portion of Panduit's LeadFrame Jack offering will be discontinued. Please part number list for affected products.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2022	10	3
Old product discontinuation date*	2022	12	14

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

CUSTOMER SERVICE CONTACTS

ASIA PACIFIC	AUSTRALIA: 1-800 7263848 AUS-CSVM@panduit.com	CHINA: 400-820-1900 CHN-CustomerService@panduit.com	HONG KONG: 800-965768 CHN-CustomerService@panduit.com	
	INDIA: 000 800 6501844 (Fixed) 000 800 6500369 (Mobile) SGP-Customer_Service@panduit.com	INDONESIA: 001 803 65 7571 SGP-Customer_Service@panduit.com	JAPAN: +81-3-6863-6000 JPN-CS@panduit.com	
	KOREA: 02-2182-7300 KOR-CustomerService@panduit.com	MALAYSIA 1800 801435 SGP-Customer_Service@panduit.com	SINGAPORE: 1-800-7263848 SGP-Customer_Service@panduit.com	
	TAIWAN: 0080 165 1487 SGP-Customer_Service@panduit.com	THAILAND: 001-800-65-6385 SGP-Customer_Service@panduit.com		
	LATIN AMERICA	BRAZIL 08000562613 (Toll Free) BRA-custservice@panduit.com	MEXICO: +52-33-37776000 x80520 01 800 360 86 00 (Toll Free) MEX-customerService@panduit.com	OTHER LA COUNTRIES: Phone USA 1-708-532-1800 TP-CS-INTERNATIONAL@panduit.com
NORTH AMERICA	USA & CANADA: 1-800-777-3300 cs@panduit.com	EMEA FORM C2-1003 DATE: 06 APR 21 APPR. MURILLO	EMEA: +44 208 6017219 EMEA-CustomerServices@panduit.com	

IMPACTED PART NUMBER(s)	Compatibility Type	Replacement Part 1
CJ66BLY	Compatible	CJ5E88TGBL
CJ66EIY	Compatible	CJ5E88TGEI
CJ66IGY	Compatible	CJ5E88TGIG
CJ66IWY	Compatible	CJ5E88TGIW
CJ66WHY	Compatible	CJ5E88TGWH
CJ66UBLY	No Replacement	NO-REPLACEMENT
CJ66UEIY	No Replacement	NO-REPLACEMENT
CJ66UIGY	No Replacement	NO-REPLACEMENT
CJ66UIWY	No Replacement	NO-REPLACEMENT
CJ66UWHY	No Replacement	NO-REPLACEMENT
NK5E88MAW-Q	Direct	NK5E88MAWY
NK5E88MBL-Q	Direct	NK5E88MBLY
NK5E88MBU-Q	Direct	NK5E88MBUY
NK5E88MEI-Q	Direct	NK5E88MEIY
NK5E88MGR-Q	Direct	NK5E88MGRY
NK5E88MIG-Q	Direct	NK5E88MIGY
NK5E88MIW-Q	Direct	NK5E88MIWY
NK5E88MOR-Q	Direct	NK5E88MORY
NK5E88MRD-Q	Direct	NK5E88MRDY
NK5E88MWH-Q	Direct	NK5E88MWHY
NK5E88MYL-Q	Direct	NK5E88MYLY