

**+ CORPORATE HEADQUARTERS**

707 Dayton Road  
PO Box 1040  
Ottawa, IL 61350  
USA

p: (800) 346-3119  
f: (815) 433-5109

**+ EUROPEAN HEADQUARTERS**

Westlink Commercial Park  
Unit 10  
Oranmore, Co. Galway  
Ireland

p: + 353 91 792444  
f: + 353 91 792445

**+ CELLULAR PRODUCTS GROUP**

Sokolská 71  
562 04 Ústí nad Orlicí III.  
Czech Republic

p: +420 465 521 020  
f: +420 464 647 299

**Product EOL Notice**

June 29, 2018

Model	Description
BB-856-17723	IE-MINIFIBERLINX-II/LASTGASP TP-TX/FX-MM1300-SC
BB-856-17727	IE-MINIFIBERLINX-II/LASTGASP,TP-TX/FX-1310+-SC
BB-856-17729	IEMINIFIBERLINXII/LSTGSP TP-TX/FX-SM1310/LONG-SC
BB-856-17742	IEMINIFIBERLINXII,LSTGSP,TP,TX/SSFY-SC 1310/1550
BB-856-17743	IEMiniFiberlinXII,LSTGSP,TX/SSFY-SM-SC,1550/1310
BB-856-19717	IE-MiniFiberlinX-II, TP-TX/FX-MM850-ST
BB-856-19718	IE-MiniFiberlinX-II, TP-TX/FX-MM850-SC
BB-856-19722	IE-MiniFiberlinX-II, TP-TX/FX-MM1300-ST
BB-856-19723	IE-MINIFIBERLINX-II, 10/100 MBPS, MM 1300SC 5KM
BB-856-19724	IE-MiniFiberlinX-II, TP-TX/FX-SM1310/PLUS-ST
BB-856-19725	IE-MINIFIBERLINX-II, 10/100 MBPS,SM 1310SC 30KM
BB-856-19727	IE-MiniFiberlinX-II, TP-TX/FX-SM1310/LONG-SC
BB-856-19752	IEMiniFiberlinXII,TP-TX/SSFY -SM-SC 1310T/1550R
BB-856-19753	IEMiniFiberlinXII,TP-TX/SSFY -SM-SC 1550T/1310R
BB-856-19755	IE-MiniFiberlinX-II,TP-TX/SSFY/PLS-SC1550T/1310R
BB-856-19757	IEMiniFiberlinXII,TP-TX/SSFY -SM-SC,1550T/1310R
BB-856-19762	TP-TX/SSFY -SM1310-SC (W/O AC ADAPTER)

This is the end-of-life announcement for the products listed above. Last time buy orders will be accepted until September 30, 2018.

**Product Migration Path:**

Current	Replacement
BB-856-17723	No replacement
BB-856-17727	No replacement
BB-856-17729	No replacement
BB-856-17742	No replacement
BB-856-17743	No replacement
BB-856-19717	BB-858-18121, BB-808-38101
BB-856-19718	BB-858-18121, BB-808-38101
BB-856-19722	BB-858-18121, BB-808-38102
BB-856-19723	BB-858-18121, BB-808-38102
BB-856-19724	BB-858-18121, BB-808-38104
BB-856-19725	BB-858-18121, BB-808-38104
BB-856-19727	BB-858-18121, BB-808-38105
BB-856-19752	BB-858-18121, BB-808-38121
BB-856-19753	BB-858-18121, BB-808-38122
BB-856-19755	BB-858-18121, BB-808-38124
BB-856-19757	BB-858-18121, BB-808-38124
BB-856-19762	BB-858-18121, BB-808-38104

**+ CORPORATE  
HEADQUARTERS**

707 Dayton Road  
PO Box 1040  
Ottawa, IL 61350  
USA

p: (800) 346-3119  
f: (815) 433-5109

Contact B+B SmartWorx for availability. Full product documentation is available on our website [www.advantech-bb.com](http://www.advantech-bb.com), or via our support staff: [support@advantech-bb.com](mailto:support@advantech-bb.com)

**+ EUROPEAN  
HEADQUARTERS**

Westlink Commercial Park  
Unit 10  
Oranmore, Co. Galway  
Ireland

p: + 353 91 792444  
f: + 353 91 792445

Thank You,



Stan Simmons | Product Sales Manager

**+ CELLULAR  
PRODUCTS GROUP**

Sokolská 71  
562 04 Ústí nad Orlicí III.  
Czech Republic

p: +420 465 521 020  
f: +420 464 647 299