

Doc. No. : PDN140701

Date : 2014/7/30

To : Dear Valued Customers

Product Discontinuance Notice

<p>Subject : The CDBA5817-G & CDBA5817-HF & CDBA5818-HF product discontinue.</p>	
<p>Parts Affected : CDBA5817-G & CDBA5817-HF & CDBA5818-HF</p>	
<p>Reason for Discontinuance : Due to low demand, these parts are discontinued.</p>	
<p>Alternative Products :</p> <ol style="list-style-type: none">1. CDBA5819-G products can replace the CDBA5817-G.2. CDBA5819-HF products can replace the CDBA5817-HF & CDBA5818-HF.3. Please contact sales person or manufacturer's representative.	
<p>Effective Date : 2014/7/30</p>	
<p>R&D Dept. Signature :</p> <p><i>Oscar ma</i></p>	<p>QA Dept. Signature :</p> <p><i>Kevin Tseng</i></p>