



# Product Change Notice

PCN Number: 13-1040-01  
Issue Date: 13-MARCH-2014

Exar Corporation

[www.exar.com](http://www.exar.com) | Support: [customersupport@exar.com](mailto:customersupport@exar.com)

**PRODUCTS AFFECTED:**

SPX1431M1-L/TR  
SPX1431M1-L  
SPX431LM1-L/TR  
SPX431LM1-L

**CHANGE CATEGORY:**

- |  |                                    |   |
|--|------------------------------------|---|
| <input type="checkbox"/> Material                                  | <input type="checkbox"/> Process   | <input type="checkbox"/> Package          |
| <input type="checkbox"/> Design                                    | <input type="checkbox"/> Datasheet | <input type="checkbox"/> Packing/Shipping |
| <input checked="" type="checkbox"/> Other: Alternate Assembly Site |                                    |   |

**DESCRIPTION OF CHANGE:**

Qualification of an alternate SOT89 package assembly site, Greatek, Taiwan, in addition to the current qualified assembly site, Cirtek, Philippines.

**IMPACT OF CHANGE:**

There is no change to product form, fit or function.

**TARGET IMPLEMENTATION DATE:** 13-JUNE-2014

Please contact customer support ([customersupport@exar.com](mailto:customersupport@exar.com)) for sample date availability or qualification data

**PROPRIETARY INFORMATION**

THIS DOCUMENT CONTAINS INFORMATION WHICH IS THE EXCLUSIVE PROPERTY OF EXAR CORPORATION. DISTRIBUTION, REPRODUCTION OR USE BY OTHERS IS NOT PERMITTED WITHOUT THE EXPRESS WRITTEN AUTHORIZATION OF EXAR CORPORATION.