

Product Obsolescence Memo

TRIMPOT® TRIMMING POTENTIOMETERS



May, 2016

Bourns® Model TC33B 3 mm SMD Trimpot® Trimming Potentiometers to be Discontinued

Bourns has decided to discontinue the [Model TC33B](#) 3 mm SMD Trimpot® Trimming Potentiometers. A lack of sales volume and diminishing demand necessitates this action. Regrettably, no replacement part numbers are available at this time.

| Obsolete Part Numbers |
|-----------------------|
| TC33B-1-101E |
| TC33B-1-102E |
| TC33B-1-103E |
| TC33B-1-104E |
| TC33B-1-105E |
| TC33B-1-201E |
| TC33B-1-202E |
| TC33B-1-203E |
| TC33B-1-204E |
| TC33B-1-501E |
| TC33B-1-502E |
| TC33B-1-503E |
| TC33B-1-504E |
| TC33B-1-472E |

Please plan for the following deadlines:

Last time buy date: July 26, 2016

Should you have any questions or need additional information, please feel free to contact [Customer Service/Inside Sales](#).