




# PRODUCT OBSOLESCENCE MEMO

## MAGNETICS



## Bourns® Model FSR1013 Radial Lead Shielded Inductor Series to be Discontinued

Riverside, California – April 28, 2021 – In accordance with our ongoing product lifecycle management procedure, Bourns will transfer the [Model FSR1013 Radial Lead Shielded Inductor Series](#) to an End of Product Life status on November 1, 2021. A lack of sales volume and diminishing demand necessitates this action. A list of affected part numbers is included below.

Obsolete Part Numbers					
FSR1013-102KL	FSR1013-152KL	FSR1013-222KL	FSR1013-332KL	FSR1013-472KL	FSR1013-822KL
FSR1013-103KL	FSR1013-153KL	FSR1013-223KL	FSR1013-333KL	FSR1013-473KL	
FSR1013-122KL	FSR1013-182KL	FSR1013-272KL	FSR1013-392KL	FSR1013-562KL	
FSR1013-123KL	FSR1013-183KL	FSR1013-273KL	FSR1013-393KL	FSR1013-682KL	

Regrettably, no replacement part numbers are available at this time. Customers may continue to purchase this product during the End of Product Life transition period between now and November 1, 2021. Orders for discontinued product during this End of Product Life transition period will be considered noncancellable. Products purchased during this End of Product Life transition period will be considered nonreturnable and will be covered by Bourns' standard warranty.

Please plan for the following deadlines:

Last time buy date: **November 1, 2021**

Last time ship date: **May 1, 2022**

If you have any questions or need additional information, please feel free to contact [Customer Service/Inside Sales](#).

IC2145