



Product Change Notification

TE Connectivity

Product Change Notification: E-19-018553-C

PCN Date: 21-JUL-21

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

521253_HOUSING, RECEPTACLE, FASTON OR POSITIVE-LOCK, 6.35 [.250] SERIES

Description of Changes

Due to the global market shift from UL-V2 resins to UL-V0 resins, TE will be consolidating resins globally eliminating UL-V2 housings and offering UL-V0 alternatives in response to this shift. All new UL-V0 alternatives will meet or exceed the performance levels of the UL-V2 housings being replaced. The following part numbers: 521253-1 and 521253-2 is being superseded by 4-521253-1 and 1-521253-2. Other part numbers are being revised to match drawing revision. Obsolete 4-521253-2 due to duplication of 1-521253-2.

Reason for Cancellation:

After further consideration, the V2 resin will remain active to continue giving customers an option especially as we navigate through global resin shortages.

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| 1-521253-2 | NO | | | | | | |
| 1-521253-7 | NO | | | | | | |
| 4-521253-1 | NO | | | | | | |
| 5-521253-1 | NO | | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| 1-521253-2 | NO | | | | | | |
| 1-521253-7 | NO | | | | | | |
| 4-521253-1 | NO | | | | | | |
| 5-521253-1 | NO | | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| 1-521253-2 | NO | | | | | | |
| 1-521253-7 | NO | | | | | | |
| 4-521253-1 | NO | | | | | | |
| 5-521253-1 | NO | | | | | | |