

## 1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type				
01	002	012	0000000529	0031.3573	Circuit protection	FAU socket	n/a
				0031.3577		FAU socket	n/a
				0031.3571		FAU 5x20	n/a
				0031.3572		FAU 6.3x32	n/a
				0031.3581		FAU 6.3x32	n/a
				0031.3583		FAU 6.3x32	n/a
				0031.3584		FAU 5x20	n/a
				3-109-711		FAU 6.3x32	n/a
				3-109-722		FAU 5x20	n/a
				3-109-723		FAU 6.3x32	n/a
				3-109-724		FAU 6.3x32	n/a
				3-109-725		FAU 5x20	n/a

\*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

## 2 Type of change

- Improved packaging

## 3 Detailed description of change

The packaging has been improved to prevent the parts from moving inside and the pins from being bent. In addition, the processability of the packaging has been improved by adding a notch in the foam.



## 4 Reason of change

- Reduce the risk of damaged parts
- Improve the handling of the package foam

## 5 Release date

The change will be rolled-out starting ww 08/2020 (Date code 2008 or higher on label) depending on the variant.

Product Change Notification					Improved FAU packaging		
owner	creation date	release date	released by	change order no	rev	page	D10-039-095
dislercy	26.08.2019	05.11.2019	bucherfa	2018210	A	1 of 2	

**6 Impact of change and recommended action**

Form	No	No change in form
Fit	No	No change for dimension
Function	No	No change in function
Manufacturing	No	No change for manufacturing site
Label	No	No change on label
Packaging	Yes	Foam insert improved

**7 Reference Documents / Attachments**

Kind of document	Remarks
<a href="#">Data Sheet</a>	FAU

Product Change Notification					Improved FAU packaging		
owner	creation date	release date	released by	change order no	rev	page	D10-039-095
dislercy	26.08.2019	05.11.2019	bucherfa	2018210	A	2 of 2	