



November 2011


NMB 4715KL Fan Series Part Numbering Change Notice

Flange Type: P00 to E00


P00 = 50K hrs. vs E00 = 100K hrs.

- Same Mechanical - - No changes in Dimensions
- This change is basically a design improvement and no changes in form, fit, and function. Both series have the same electrical and mechanical characteristics.
- This change is a positive one. The E series impellers / stators assembly are more robust construction and provide greater shaft stability than the old P series.

Fan Impeller Assembly Design Improvement



Fan Stator Assembly Design Improvement



- Should you have any questions, please contact your NMB Account Manager or Product Support Rep.