



Harwin plc
Fitzherbert Road
Farlington, Portsmouth
Hampshire PO6 1RT
United Kingdom

Reception: +44 (0)23 9231 4545
Sales Desk: +44 (0)23 9237 0451

Wednesday 3rd February, 2021

Dear Customer,

Re: Product Change Notification for Harwin product.

As part of our continuous improvement process, please be advised that the following ranges of male Datamate L-Tek are now being manufactured with a different plastic material:

- M80-753
- M80-754
- M80-771
- M80-782
- M80-792
- M80-841
- M80-842
- M80-843
- M80-851
- M80-852
- M80-853
- M80-854
- M80-882

Please see the attached spreadsheet for a more detailed list of affected items, also available in Excel format here:

https://cdn.harwin.com/pdfs/PCN_spreadsheet_03-Feb-2021.xlsx

The plastic material used on these connectors was a grade of 30% Glass-filled Polyamide 46. We are now using a grade of 30% Glass-filled PPS. This change will not affect the dimensions, electrical or mechanical performance, or appearance of the connectors. The same PPS material is already used on the J-Tek and Mix-Tek versions of Datamate.

Stocks of the most popular products are now being manufactured in PPS, and other lines will be converted as stocks are diminished of the existing plastic housings. If you need to confirm which material you have been shipped, please advise the part number and batch number to our Customer Services Team on sales@harwin.co.uk, and they will supply this information.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Change Team
technical@harwin.com

Product Change Notification from Harwin

Part number affected	Drawing showing new material
M80-7530422	M80-753.pdf
M80-7530442	M80-753.pdf
M80-7530445	M80-753.pdf
M80-7530622	M80-753.pdf
M80-7530642	M80-753.pdf
M80-7530645	M80-753.pdf
M80-7530822	M80-753.pdf
M80-7530842	M80-753.pdf
M80-7530845	M80-753.pdf
M80-7531022	M80-753.pdf
M80-7531042	M80-753.pdf
M80-7531045	M80-753.pdf
M80-7531222	M80-753.pdf
M80-7531242	M80-753.pdf
M80-7531245	M80-753.pdf
M80-7531422	M80-753.pdf
M80-7531442	M80-753.pdf
M80-7531445	M80-753.pdf
M80-7531622	M80-753.pdf
M80-7531642	M80-753.pdf
M80-7531645	M80-753.pdf
M80-7531822	M80-753.pdf
M80-7531842	M80-753.pdf
M80-7531845	M80-753.pdf
M80-7532022	M80-753.pdf
M80-7532042	M80-753.pdf
M80-7532045	M80-753.pdf
M80-7532622	M80-753.pdf
M80-7532642	M80-753.pdf
M80-7532645	M80-753.pdf
M80-7533422	M80-753.pdf
M80-7533442	M80-753.pdf
M80-7533445	M80-753.pdf
M80-7534422	M80-753.pdf
M80-7534442	M80-753.pdf
M80-7534445	M80-753.pdf
M80-7540422	M80-754.pdf
M80-7540442	M80-754.pdf
M80-7540445	M80-754.pdf
M80-7540622	M80-754.pdf
M80-7540645	M80-754.pdf
M80-7540822	M80-754.pdf
M80-7540842	M80-754.pdf
M80-7540845	M80-754.pdf
M80-7541022	M80-754.pdf
M80-7541042	M80-754.pdf
M80-7541045	M80-754.pdf
M80-7541222	M80-754.pdf
M80-7541242	M80-754.pdf
M80-7541245	M80-754.pdf
M80-7541422	M80-754.pdf
M80-7541445	M80-754.pdf
M80-7541622	M80-754.pdf
M80-7541642	M80-754.pdf
M80-7541645	M80-754.pdf
M80-7541822	M80-754.pdf
M80-7541842	M80-754.pdf
M80-7541845	M80-754.pdf
M80-7542022	M80-754.pdf
M80-7542042	M80-754.pdf
M80-7542045	M80-754.pdf
M80-7542622	M80-754.pdf
M80-7542642	M80-754.pdf

Product Change Notification from Harwin

Part number affected	Drawing showing new material
M80-7542645	M80-754.pdf
M80-7543422	M80-754.pdf
M80-7543442	M80-754.pdf
M80-7543445	M80-754.pdf
M80-7544422	M80-754.pdf
M80-7544442	M80-754.pdf
M80-7544445	M80-754.pdf
M80-7710422	M80-771.pdf
M80-7710442	M80-771.pdf
M80-7710445	M80-771.pdf
M80-7710622	M80-771.pdf
M80-7710642	M80-771.pdf
M80-7710645	M80-771.pdf
M80-7710822	M80-771.pdf
M80-7710842	M80-771.pdf
M80-7710845	M80-771.pdf
M80-7711022	M80-771.pdf
M80-7711042	M80-771.pdf
M80-7711045	M80-771.pdf
M80-7711222	M80-771.pdf
M80-7711242	M80-771.pdf
M80-7711245	M80-771.pdf
M80-7711422	M80-771.pdf
M80-7711442	M80-771.pdf
M80-7711445	M80-771.pdf
M80-7711622	M80-771.pdf
M80-7711642	M80-771.pdf
M80-7711645	M80-771.pdf
M80-7711822	M80-771.pdf
M80-7711842	M80-771.pdf
M80-7711845	M80-771.pdf
M80-7712022	M80-771.pdf
M80-7712042	M80-771.pdf
M80-7712045	M80-771.pdf
M80-7712622	M80-771.pdf
M80-7712642	M80-771.pdf
M80-7712645	M80-771.pdf
M80-7713422	M80-771.pdf
M80-7713442	M80-771.pdf
M80-7713445	M80-771.pdf
M80-7714422	M80-771.pdf
M80-7714442	M80-771.pdf
M80-7714445	M80-771.pdf
M80-7820222	M80-782.pdf
M80-7820242	M80-782.pdf
M80-7820245	M80-782.pdf
M80-7820322	M80-782.pdf
M80-7820342	M80-782.pdf
M80-7820345	M80-782.pdf
M80-7820422	M80-782.pdf
M80-7820442	M80-782.pdf
M80-7820445	M80-782.pdf
M80-7820522	M80-782.pdf
M80-7820542	M80-782.pdf
M80-7820545	M80-782.pdf
M80-7820622	M80-782.pdf
M80-7820642	M80-782.pdf
M80-7820645	M80-782.pdf
M80-7820722	M80-782.pdf
M80-7820742	M80-782.pdf
M80-7820745	M80-782.pdf
M80-7920222	M80-792.pdf
M80-7920242	M80-792.pdf

Product Change Notification from Harwin

Part number affected	Drawing showing new material
M80-7920245	M80-792.pdf
M80-7920322	M80-792.pdf
M80-7920342	M80-792.pdf
M80-7920345	M80-792.pdf
M80-7920422	M80-792.pdf
M80-7920442	M80-792.pdf
M80-7920445	M80-792.pdf
M80-7920522	M80-792.pdf
M80-7920542	M80-792.pdf
M80-7920545	M80-792.pdf
M80-7920622	M80-792.pdf
M80-7920642	M80-792.pdf
M80-7920645	M80-792.pdf
M80-7920722	M80-792.pdf
M80-7920742	M80-792.pdf
M80-7920745	M80-792.pdf
M80-8410442	M80-841.pdf
M80-8410445	M80-841.pdf
M80-8410642	M80-841.pdf
M80-8410645	M80-841.pdf
M80-8410842	M80-841.pdf
M80-8410845	M80-841.pdf
M80-8411042	M80-841.pdf
M80-8411045	M80-841.pdf
M80-8411242	M80-841.pdf
M80-8411245	M80-841.pdf
M80-8411442	M80-841.pdf
M80-8411445	M80-841.pdf
M80-8411642	M80-841.pdf
M80-8411645	M80-841.pdf
M80-8411842	M80-841.pdf
M80-8411845	M80-841.pdf
M80-8412042	M80-841.pdf
M80-8412045	M80-841.pdf
M80-8412642	M80-841.pdf
M80-8412645	M80-841.pdf
M80-8413442	M80-841.pdf
M80-8413445	M80-841.pdf
M80-8414442	M80-841.pdf
M80-8414445	M80-841.pdf
M80-8420222	M80-842.pdf
M80-8420242	M80-842.pdf
M80-8420245	M80-842.pdf
M80-8420322	M80-842.pdf
M80-8420342	M80-842.pdf
M80-8420345	M80-842.pdf
M80-8420422	M80-842.pdf
M80-8420442	M80-842.pdf
M80-8420445	M80-842.pdf
M80-8420522	M80-842.pdf
M80-8420542	M80-842.pdf
M80-8420545	M80-842.pdf
M80-8420622	M80-842.pdf
M80-8420642	M80-842.pdf
M80-8420645	M80-842.pdf
M80-8420722	M80-842.pdf
M80-8420742	M80-842.pdf
M80-8420745	M80-842.pdf
M80-8430242	M80-843.pdf
M80-8430245	M80-843.pdf
M80-8430342	M80-843.pdf
M80-8430345	M80-843.pdf
M80-8430442	M80-843.pdf

Product Change Notification from Harwin

Part number affected	Drawing showing new material
M80-8430445	M80-843.pdf
M80-8430542	M80-843.pdf
M80-8430545	M80-843.pdf
M80-8430642	M80-843.pdf
M80-8430645	M80-843.pdf
M80-8430742	M80-843.pdf
M80-8430745	M80-843.pdf
M80-8510422	M80-851.pdf
M80-8510442	M80-851.pdf
M80-8510445	M80-851.pdf
M80-8510622	M80-851.pdf
M80-8510642	M80-851.pdf
M80-8510645	M80-851.pdf
M80-8510822	M80-851.pdf
M80-8510842	M80-851.pdf
M80-8510845	M80-851.pdf
M80-8511022	M80-851.pdf
M80-8511042	M80-851.pdf
M80-8511045	M80-851.pdf
M80-8511222	M80-851.pdf
M80-8511242	M80-851.pdf
M80-8511245	M80-851.pdf
M80-8511422	M80-851.pdf
M80-8511442	M80-851.pdf
M80-8511445	M80-851.pdf
M80-8511622	M80-851.pdf
M80-8511642	M80-851.pdf
M80-8511645	M80-851.pdf
M80-8511822	M80-851.pdf
M80-8511842	M80-851.pdf
M80-8511845	M80-851.pdf
M80-8512022	M80-851.pdf
M80-8512042	M80-851.pdf
M80-8512045	M80-851.pdf
M80-8512622	M80-851.pdf
M80-8512642	M80-851.pdf
M80-8512645	M80-851.pdf
M80-8513422	M80-851.pdf
M80-8513442	M80-851.pdf
M80-8513445	M80-851.pdf
M80-8514422	M80-851.pdf
M80-8514442	M80-851.pdf
M80-8514445	M80-851.pdf
M80-8520222	M80-852.pdf
M80-8520242	M80-852.pdf
M80-8520245	M80-852.pdf
M80-8520322	M80-852.pdf
M80-8520342	M80-852.pdf
M80-8520345	M80-852.pdf
M80-8520422	M80-852.pdf
M80-8520442	M80-852.pdf
M80-8520445	M80-852.pdf
M80-8520522	M80-852.pdf
M80-8520542	M80-852.pdf
M80-8520545	M80-852.pdf
M80-8520622	M80-852.pdf
M80-8520642	M80-852.pdf
M80-8520645	M80-852.pdf
M80-8520722	M80-852.pdf
M80-8520742	M80-852.pdf
M80-8520745	M80-852.pdf
M80-8530422	M80-853.pdf
M80-8530442	M80-853.pdf

Product Change Notification from Harwin

Part number affected	Drawing showing new material
M80-8530445	M80-853.pdf
M80-8530622	M80-853.pdf
M80-8530642	M80-853.pdf
M80-8530645	M80-853.pdf
M80-8530822	M80-853.pdf
M80-8530842	M80-853.pdf
M80-8530845	M80-853.pdf
M80-8531022	M80-853.pdf
M80-8531042	M80-853.pdf
M80-8531045	M80-853.pdf
M80-8531222	M80-853.pdf
M80-8531242	M80-853.pdf
M80-8531245	M80-853.pdf
M80-8531422	M80-853.pdf
M80-8531442	M80-853.pdf
M80-8531445	M80-853.pdf
M80-8531622	M80-853.pdf
M80-8531642	M80-853.pdf
M80-8531645	M80-853.pdf
M80-8531822	M80-853.pdf
M80-8531842	M80-853.pdf
M80-8531845	M80-853.pdf
M80-8532022	M80-853.pdf
M80-8532042	M80-853.pdf
M80-8532045	M80-853.pdf
M80-8532642	M80-853.pdf
M80-8532645	M80-853.pdf
M80-8533422	M80-853.pdf
M80-8533442	M80-853.pdf
M80-8533445	M80-853.pdf
M80-8534422	M80-853.pdf
M80-8534442	M80-853.pdf
M80-8534445	M80-853.pdf
M80-8540422	M80-854.pdf
M80-8540442	M80-854.pdf
M80-8540445	M80-854.pdf
M80-8540622	M80-854.pdf
M80-8540642	M80-854.pdf
M80-8540645	M80-854.pdf
M80-8540822	M80-854.pdf
M80-8540842	M80-854.pdf
M80-8540845	M80-854.pdf
M80-8541022	M80-854.pdf
M80-8541042	M80-854.pdf
M80-8541045	M80-854.pdf
M80-8541222	M80-854.pdf
M80-8541242	M80-854.pdf
M80-8541245	M80-854.pdf
M80-8541422	M80-854.pdf
M80-8541442	M80-854.pdf
M80-8541445	M80-854.pdf
M80-8541622	M80-854.pdf
M80-8541642	M80-854.pdf
M80-8541645	M80-854.pdf
M80-8541822	M80-854.pdf
M80-8541842	M80-854.pdf
M80-8541845	M80-854.pdf
M80-8542022	M80-854.pdf
M80-8542042	M80-854.pdf
M80-8542045	M80-854.pdf
M80-8542622	M80-854.pdf
M80-8542642	M80-854.pdf
M80-8542645	M80-854.pdf

Product Change Notification from Harwin

Part number affected	Drawing showing new material
M80-8543422	M80-854.pdf
M80-8543442	M80-854.pdf
M80-8543445	M80-854.pdf
M80-8544422	M80-854.pdf
M80-8544442	M80-854.pdf
M80-8544445	M80-854.pdf
M80-8820222	M80-882.pdf
M80-8820242	M80-882.pdf
M80-8820245	M80-882.pdf
M80-8820322	M80-882.pdf
M80-8820342	M80-882.pdf
M80-8820345	M80-882.pdf
M80-8820422	M80-882.pdf
M80-8820442	M80-882.pdf
M80-8820445	M80-882.pdf
M80-8820522	M80-882.pdf
M80-8820542	M80-882.pdf
M80-8820545	M80-882.pdf
M80-8820622	M80-882.pdf
M80-8820642	M80-882.pdf
M80-8820645	M80-882.pdf
M80-8820722	M80-882.pdf
M80-8820742	M80-882.pdf
M80-8820745	M80-882.pdf