




PRODUCT CHANGE NOTIFICATION

SINGLFUSE SMD FUSES



Bourns® Model SF-xxxxxxx-M/SF-xxxxxxxA-M, SF-xxxxxxx-F, and SF-xxxxxxx-W/SF-xxxxxxxA-W Series SinglFuse™ SMD Fuses

Change to Company Brand Identification on Label


Riverside, California – January 17, 2022 – Effective April 3, 2022, Bourns will change the company brand identification on the label of the taping reel and packaging bag from “BOURNS INC.” to the Bourns trademark “**BOURNS®**” for the [Model SF-xxxxxxx-M/SF-xxxxxxxA-M, SF-xxxxxxx-F and SF-xxxxxxx-W/SF-xxxxxxxA-W Series SinglFuse™ SMD Fuses](#).

The fit, form, function, quality, and reliability of the affected models will not be impacted by this label change. Bourns will start to implement this label change on April 3, 2022.

Affected Series	Original	New
SF-xxxxxxx-F SF-xxxxxxx-M SF-xxxxxxxA-M	<p>BOURNS INC.</p>  <p>P/N: SF-1206S050M-2 QTY: 4000 D/C: 1702 LOT NO: F1766969 MADE IN: CHINA</p> <p>RoHS    1</p>	<p>BOURNS®</p>  <p>P/N: SF-1206S050M-2 QTY: 4000 D/C: 2152 LOT NO: F1766969 MADE IN: CHINA</p> <p>RoHS    1</p>

Users should verify that the described changes will not impact the performance of the product in their specific applications.

SF2201

Affected Series	Original	New
SF-xxxxxxx-W SF-xxxxxxxA-W	<p>BOURNS INC.</p>  <p>P/N: SF-2410EP075W-2 QTY: 2000 D/C: 1702 LOT NO: A1766966 MADE IN: CHINA</p> <p>RoHS    1</p>	<p>BOURNS®</p>  <p>P/N: SF-2410EP075W-2 QTY: 2000 D/C: 2152 LOT NO: A1766966 MADE IN: CHINA</p> <p>RoHS    1</p>
SF-xxxxxxx-W SF-xxxxxxxA-W	<p>BOURNS INC.</p>  <p>P/N: SF-2410EP050W-2 QTY: 2000 D/C: 1702 LOT NO: A1766966 MADE IN: CHINA</p> <p>RoHS     1</p>	<p>BOURNS®</p>  <p>P/N: SF-2410EP050W-2 QTY: 2000 D/C: 2152 LOT NO: A1766966 MADE IN: CHINA</p> <p>RoHS     1</p>
SF-2410SP-W	<p>BOURNS INC.</p>  <p>P/N: SF-2410SP050W-2 QTY: 2000 D/C: 1702 LOT NO: M1766962 MADE IN: CHINA</p> <p>RoHS     1</p>	<p>BOURNS®</p>  <p>P/N: SF-2410SP050W-2 QTY: 2000 D/C: 2152 LOT NO: M1766962 MADE IN: CHINA</p> <p>RoHS     1</p>

Implementation dates are as follows:

Date that existing package tape carrier will cease: *April 2, 2022*
 Date that modified package tape carrier will begin: *April 3, 2022*
 First date code using the above changes: *2214*

If you have any questions or need additional information, please feel free to [contact Customer Service/Inside Sales](#).

Affected Part Numbers – SF-xxxxxx-F series

SF-0402FP-F		SF-0603FP-F		SF-0603HI-F
SF-0402FP020F-2	SF-0402FP200F-2	SF-0603FP015F-2	SF-0603FP175F-2	SF-0603HI050F-2
SF-0402FP025F-2	SF-0402FP250F-2	SF-0603FP020F-2	SF-0603FP200F-2	SF-0603HI075F-2
SF-0402FP0375F-2	SF-0402FP300F-2	SF-0603FP025F-2	SF-0603FP250F-2	SF-0603HI100F-2
SF-0402FP050F-2	SF-0402FP350F-2	SF-0603FP0375F-2	SF-0603FP300F-2	SF-0603HI150F-2
SF-0402FP075F-2	SF-0402FP400F-2	SF-0603FP050F-2	SF-0603FP350F-2	SF-0603HI200F-2
SF-0402FP100F-2	SF-0402FP500F-2	SF-0603FP075F-2	SF-0603FP400F-2	SF-0603HI250F-2
SF-0402FP125F-2		SF-0603FP100F-2	SF-0603FP500F-2	SF-0603HI300F-2
SF-0402FP150F-2		SF-0603FP125F-2		SF-0603HI350F-2
SF-0402FP175F-2		SF-0603FP150F-2		SF-0603HI400F-2

Affected Part Numbers – SF-xxxxxx-M series

SF-0402S-M	SF-0603FP-M	SF-0603SP-M	SF-0603S-M	SF-0603SP-M	SF-0603HI-M	SF-0603HIA-M
SF-0402S050M-2	SF-0603FP050M-2	SF-0603S050M-2	SF-0603SP100M-2	SF-0603HI100M-2	SF-0603HI100M-2	SF-0603HIA100M-2
SF-0402S075M-2	SF-0603FP075M-2	SF-0603S075M-2	SF-0603SP150M-2	SF-0603HI150M-2	SF-0603HI150M-2	SF-0603HIA150M-2
SF-0402S100M-2	SF-0603FP100M-2	SF-0603S100M-2	SF-0603SP200M-2	SF-0603HI200M-2	SF-0603HI200M-2	SF-0603HIA200M-2
SF-0402S150M-2	SF-0603FP125M-2	SF-0603S150M-2	SF-0603SP250M-2	SF-0603HI250M-2	SF-0603HI250M-2	SF-0603HIA300M-2
SF-0402S200M-2	SF-0603FP150M-2	SF-0603S200M-2	SF-0603SP300M-2	SF-0603HI300M-2	SF-0603HI300M-2	SF-0603HIA350M-2
SF-0402S300M-2	SF-0603FP175M-2	SF-0603S250M-2	SF-0603SP350M-2	SF-0603HI350M-2	SF-0603HI350M-2	SF-0603HIA400M-2
SF-0402S400M-2	SF-0603FP200M-2	SF-0603S300M-2	SF-0603SP400M-2	SF-0603HI400M-2	SF-0603HI400M-2	SF-0603HIA450M-2
	SF-0603FP250M-2	SF-0603S350M-2	SF-0603SP450M-2	SF-0603HI450M-2	SF-0603HI450M-2	SF-0603HIA500M-2
	SF-0603FP300M-2	SF-0603S400M-2	SF-0603SP500M-2	SF-0603HI500M-2	SF-0603HI500M-2	
	SF-0603FP350M-2	SF-0603S500M-2	SF-0603SP600M-2	SF-0603HI600M-2	SF-0603HI600M-2	
	SF-0603FP400M-2	SF-0603S600M-2	SF-0603SP700M-2	SF-0603HI700M-2	SF-0603HI700M-2	
	SF-0603FP450M-2		SF-0603SP800M-2	SF-0603HI800M-2	SF-0603HI800M-2	
	SF-0603FP500M-2					

Affected Part Numbers – SF-xxxxxx-M series

SF-0603SA-M	SF-1206S-M	SF-1206SP-M	SF-1206HH-M	SF-1206HI-M	SF-1206HIA-M	SF-0603HIA-M
SF-0603SA050M-2	SF-1206S050M-2	SF-1206SP100M-2	SF-1206HH10M-2	SF-1206HI050M-2	SF-1206HIA050M-2	SF-0603HIA100M-2
SF-0603SA075M-2	SF-1206S075M-2	SF-1206SP125M-2	SF-1206HH12M-2	SF-1206HI075M-2	SF-1206HIA075M-2	SF-0603HIA150M-2
SF-0603SA100M-2	SF-1206S100M-2	SF-1206SP150M-2	SF-1206HH15M-2	SF-1206HI100M-2	SF-1206HIA100M-2	SF-0603HIA200M-2
SF-0603SA125M-2	SF-1206S150M-2	SF-1206SP200M-2	SF-1206HH20M-2	SF-1206HI150M-2	SF-1206HIA150M-2	SF-0603HIA300M-2
SF-0603SA150M-2	SF-1206S175M-2	SF-1206SP250M-2	SF-1206HH25M-2	SF-1206HI200M-2	SF-1206HIA200M-2	SF-0603HIA350M-2
SF-0603SA200M-2	SF-1206S200M-2	SF-1206SP300M-2	SF-1206HH30M-2	SF-1206HI250M-2	SF-1206HIA300M-2	SF-0603HIA400M-2
SF-0603SA250M-2	SF-1206S250M-2	SF-1206SP350M-2		SF-1206HI300M-2	SF-1206HIA350M-2	SF-0603HIA450M-2
SF-0603SA300M-2	SF-1206S300M-2	SF-1206SP400M-2	SF-1206HV-M	SF-1206HI350M-2	SF-1206HIA400M-2	SF-0603HIA500M-2
SF-0603SA350M-2	SF-1206S400M-2	SF-1206SP450M-2	SF-1206HV10M-2	SF-1206HI400M-2	SF-1206HIA450M-2	
SF-0603SA400M-2	SF-1206S500M-2	SF-1206SP500M-2	SF-1206HV12M-2	SF-1206HI450M-2	SF-1206HIA600M-2	
SF-0603SA500M-2	SF-1206S600M-2	SF-1206SP550M-2	SF-1206HV15M-2	SF-1206HI500M-2		
SF-0603SA600M-2	SF-1206S700M-2	SF-1206SP600M-2	SF-1206HV20M-2	SF-1206HI600M-2		
SF-0603SA700M-2	SF-1206S800M-2	SF-1206SP700M-2	SF-1206HV25M-2	SF-1206HI700M-2		
SF-0603SA800M-2		SF-1206SP800M-2	SF-1206HV30M-2	SF-1206HI800M-2		
			SF-1206HV40M-2			



Affected Part Numbers – SF-xxxxxx-M series

SF1206F-M	SF-1206SA-M
SF-1206F250M-2	SF-1206SA050M-2
SF-1206F300M-2	SF-1206SA075M-2
SF-1206F350M-2	SF-1206SA100M-2
SF-1206F400M-2	SF-1206SA150M-2
SF-1206F450M-2	SF-1206SA200M-2
SF-1206F500M-2	SF-1206SA250M-2
SF-1206F600M-2	SF-1206SA300M-2
SF-1206F700M-2	SF-1206SA350M-2
SF-1206F800M-2	SF-1206SA400M-2
	SF-1206SA450M-2
	SF-1206SA500M-2

Affected Part Numbers – SF-xxxxxx-W series

SF-1206S-W	SF-1206SA-W	SF-2410FP-W	SF-2410SP-W	SF-2410FPA-W	SF-2410F-W
SF-1206S150W-2	SF-1206SA150W-2	SF-2410FP050W-2	SF-2410SP050W-2	SF-2410FPA100W-2	SF-2410F1200W-2
SF-1206S160W-2	SF-1206SA160W-2	SF-2410FP063W-2	SF-2410SP063W-2	SF-2410FPA125W-2	SF-2410F1500W-2
SF-1206S200W-2	SF-1206SA200W-2	SF-2410FP075W-2	SF-2410SP080W-2	SF-2410FPA150W-2	SF-2410F2000W-2
SF-1206S250W-2	SF-1206SA250W-2	SF-2410FP100W-2	SF-2410SP100W-2	SF-2410FPA200W-2	
SF-1206S300W-2	SF-1206SA300W-2	SF-2410FP125W-2	SF-2410SP125W-2	SF-2410FPA250W-2	SF-2410FA-W
SF-1206S315W-2	SF-1206SA315W-2	SF-2410FP150W-2	SF-2410SP160W-2	SF-2410FPA300W-2	SF-2410FA1200W-2
SF-1206S350W-2	SF-1206SA350W-2	SF-2410FP200W-2	SF-2410SP200W-2	SF-2410FPA315W-2	SF-2410FA1500W-2
SF-1206S400W-2	SF-1206SA400W-2	SF-2410FP250W-2		SF-2410FPA350W-2	SF-2410FA2000W-2
SF-1206S500W-2	SF-1206SA500W-2	SF-2410FP300W-2		SF-2410FPA400W-2	
SF-1206S630W-2	SF-1206SA630W-2	SF-2410FP315W-2		SF-2410FPA500W-2	
SF-1206S700W-2	SF-1206SA700W-2	SF-2410FP350W-2		SF-2410FPA630W-2	
SF-1206S800W-2	SF-1206SA800W-2	SF-2410FP400W-2		SF-2410FPA700W-2	
SF-1206S1000W-2	SF-1206SA1000W-2	SF-2410FP500W-2		SF-2410FPA800W-2	
SF-1206S1200W-2	SF-1206SA1200W-2	SF-2410FP630W-2		SF-2410FPA1000W-2	
SF-1206S1500W-2	SF-1206SA1500W-2	SF-2410FP700W-2			
		SF-2410FP800W-2			
		SF-2410FP1000W-2			