

**1 Products affected**

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type				
02	007	012	0000002391	See list below	Appliance Outlet	5091	





\*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

List of part numbers affected						
6182.0001	6182.0002	6182.0003	6182.0004	6182.0005	6182.0006	6182.0007
6182.0008	6182.0034	6182.0037	6182.0039	6182.0040	6182.0045	6182.0046
6182.0050						

**2 Type of change**

Change of approval and rating markings on the moulding body.

**3 Detailed description of change**

Old product appearance	New product appearance
	
Old product appearance	New product appearance
Flange with through holes special type	
	

Please note that only rivet-on mounting types and special type are illustrated. However, the same changes apply to both mounting types with screw flange as listed in the affected part numbers list in chapter 1.

**4 Reason of change**

Standards update according to the new UL/CSA 60320-1

**5 Release date**

The change will be rolled out starting ww 43/2019 (Date code 1943 or higher on packaging label) and lasts approx. 6 months depending on the variant. This change has no effect on the validity of the approval certificates.

Product Change Notification					5091 Change of inscription		
owner	creation date	release date	released by	change order no	rev	page	D10-036-693
sariogar	15.05.2019	17.10.2019	blumhe	2018584	A	1 of 2	

**6 Impact of change and recommended action**

Form	Yes	Change of approval marks and rating.
Fit	No	-
Function	No	-
Manufacturing	No	-
Label	No	-
Packaging	No	-

**7 Reference Documents / Attachments**

Kind of document	Remarks
<a href="#">5091 Data Sheet</a>	

Product Change Notification					5091 Change of inscription		
owner	creation date	release date	released by	change order no	rev	page	D10-036-693
sariogar	15.05.2019	17.10.2019	blumhe	2018584	A	2 of 2	