

 <p>INNOVATOR IN ELECTRONICS</p>	<h2 style="color: red;">LFL21915MTC1A027</h2>	
	Hersteller-Teilenummer:	LFL21915MTC1A027
 <p>Not Actual Photo YIC International Co., Limited.</p>	Hersteller / Marke:	Murata Electronics
	Teil der Beschreibung:	SIGNAL CONDITIONING
Datenblätter:	 LFL21915MTC1A027.pdf	
RoHs Status:	Bleifrei / RoHS-konform	
Lagerzustand:	New original, 7990 pcs Stock Available.	
Liefern von:	Hong Kong	
Versandweg:	DHL/Fedex/TNT/UPS/EMS	
<p>Image may be representation. See specs for product details.</p>		

Spezifikationen

Teilenummer	LFL21915MTC1A027
Hersteller	Murata Electronics
Beschreibung	SIGNAL CONDITIONING
Kategorie	Filter > HF-Filter
Teilstatus	7990 pcs Stock
Serie	-
Frequenz	915MHz Center
Befestigungsart	Surface Mount
Größe / Dimension	0.079" L x 0.049" W (2.00mm x 1.25mm)
Höhe (max)	0.041" (1.05mm)
Einfügedämpfung	0.47dB
Verpackung / Gehäuse	0805 (2012 Metric), 8 PC Pad
Filtertyp	Low Pass
Bandbreite	-
Plätschern	-
Verpackung	Tape & Reel (TR)













































LFL21915MTC1A027 ist neu im Original, Suche LFL21915MTC1A027 Datenblätter, PDF, Inventar bei Y-IC.com Online, Bestellen Sie LFL21915MTC1A027 Murata Electronics mit Garantie und Vertrauen. Anfrage LFL21915MTC1A027: Info@Y-IC.com

Sie können auch interessiert sein:

 <p>Not Actual Photo YIC International Co., Limited.</p> <p>LFL21900MTF3D943 MURATA LFL21900MTF3D943 MURATA</p>	 <p>Not Actual Photo YIC International Co., Limited.</p> <p>LFL30-13C0950B020AF-357 MURATA MURATA 4532</p>	 <p>Not Actual Photo YIC International Co., Limited.</p> <p>LFL2H1G73TF1D707 MURATA MURATA SMD</p>	 <p>Not Actual Photo YIC International Co., Limited.</p> <p>LFL21875MTC1A209 MURATA LFL21875MTC1A209 MURATA</p>
 <p>Not Actual Photo YIC International Co., Limited.</p> <p>LFL21884MB148D-T(LFL21884MTCAA218) MURATA LFL21884MB148D-T(LFL21884MTCAA218) MURATA</p>	 <p>Not Actual Photo YIC International Co., Limited.</p> <p>LFL30-15C0718B076AF-916 MURATA MURATA 41206</p>	 <p>LFL21897MTC1A017 Murata Electronics SIGNAL CONDITIONING</p>	 <p>Not Actual Photo YIC International Co., Limited.</p> <p>LFL32459MTB2D238 MURATA LFL32459MTB2D238 MURATA</p>

heiße Teile

Mehr

 LFL152G45TC7C309	 LFL15829MTC	 LFL15869MTC1B787	D LFL15924MTC1A184	 LFL181G43TC1A195
 LFL181G44TC1A065	 LFL181G50TC1B757	D LFL181G74TF1D807	 LFL181G95TF1D802	 LFL181G99TC1B777
 LFL182G45TC1A108	 LFL182G45TC1A202	 LFL182G45TC3B746	 LFL182G45TD2C153	 LFL182G50TC1B905
D LFL182G50TC3C171	 LFL182G54	 LFL182G54TC1B838	 LFL183G55TC2B908	 LFL185G78TD1B873
 LFL18628MTC2C221	 LFL18685MTF1D269	 LFL18829MTCRD627	 LFL18829MTF1D897	 LFL18942MTC1A052
 LFL211G08TF3D908	 LFL211G88TC1A020	D LFL211G89TC1A029	 LFL211G92TC1A060	 LFL211G95TF2D298
 LFL212G09TC1C150	D LFL212G45TC1A007	 LFL212G45TC1A023	 LFL212G45TN1D615TEMP	 LFL215G37TC1A210
 LFL215G42TC1A216	 LFL215G51TC1A149	 LFL21847MTC1A006	 LFL21875MTC1A209	 LFL21897MTC1A017
 LFL21900MTF3D943	 LFL21902MTC1A018	 LFL32459MTB2D238	D LFL43178MAK1-480	 LFL431G66AK2-396
 LFL431G88AK2-411	 LFL43240MAK1-664	 LFL43445MAK1A332	 LFLK1608R68K-T-680N	 LFLOQ1G69TM1D511

Contact us: Info@Y-IC.com

HINZUFÜGEN: Einheit A5-B5 Nr.509, 5 / F Sing Win Fabrikgebäude, 15-17 Shing Yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited