

TAIYO YUDEN

Taiyo Yuden (U.S.A.), Inc.
10 N. Martingale Rd.
Schaumburg, IL 60173
Tel (630) 237-2405 Fax (847) 240-1715
<http://www.t-yuden.com>

Notice of Discontinuation for Taiyo Yuden (U.S.A.) Inc. Distributors

DATE: January 26th, 2017

RE: Discontinuation of Metal Wire-Wound Chip Power Inductors (MCOIL™, MB series H (High Spec.) type)

REF NO.: UTY-DN17-01D

Taiyo Yuden (U.S.A.) Inc. hereby gives notice that the following part numbers are to be discontinued effective immediately from the issue of this notice for all Taiyo Yuden (U.S.A.) Inc distributors until further notice.

Discontinued Part Number
MBPK3225H1R0M
MBPK3225H1R5M
MBPK3225H2R2M
MBPK3225H3R3M
MBPK3225H4R7M
MBPK3225HR47N
MBPK3225HR68N

NOTE: The information in this notice is applicable only to Taiyo Yuden (U.S.A.) Inc distribution sales channels. Discontinuation and promotional status changes, change schedules, and availability may vary in other regions. Please contact the Taiyo Yuden sales office responsible for sales in your country for details on this notice.

Issued by TAIYO YUDEN (U.S.A.) INC.
Sales Planning Department