

To: Digikey

October 2018

Please be informed Toshiba has announced discontinuation on the following product(s) in October 2018. Our sales records indicate you have purchased the following product(s) from Toshiba America Electronic Components in the past.

**Products**

Item No	Last Time Buy	Last Shipment	substitution Level	Replacement	Reason
DSR01S30SC(TPL3)	12/31/2019	3/31/2020	1	DSR01S30SL.L3F	Integration of products
TC7WPB8306L8X,LF(S)	12/31/2019	3/31/2020	3	TC7WPB9306FK,LF(CT)	Discontinuation of Assembly Machine

**Last Time Buy (LTB) Option**

Toshiba will support last time buy (LTB) orders received on or before the dates listed above (LTB Date). Last time buy orders for all affected products must be in place in total by LTB Date. Deliveries will be scheduled and advised accordingly after receipt of LTB orders. However, unforeseen circumstances might prevent Toshiba to support partially or fully on LTB orders. If such event occurs, we will notify you of our best support plan as soon as possible. Thank you for your understanding. Should you have any questions, please contact your sales representative.

Best Regards,

Small Signal, Logic and Linear IC Device, Discrete Business Unit  
Toshiba America Electronic Components, Inc.

=====

Substitution Level\*\*

0 = No replacement

1 = Package and characteristics are mostly same or better, not necessary to change other circuit to replace.

2 = Package and characteristics are mostly same or better, but some modification of the other circuit is necessary.

3 = Characteristics are same or better, but package/pin arrangement are different, so the other circuit modification is necessary.

4 = Other reason.