

To : Dear Valued Customers

Product Discontinuance Notice

Subject : CDBH3-54-HF Series products discontinue.											
Parts Affected :											
<table border="1" style="margin: auto; border-collapse: collapse;"> <thead> <tr> <th style="padding: 5px;">Part No.</th> <th style="padding: 5px;">Package Type</th> </tr> </thead> <tbody> <tr> <td align="center" style="padding: 5px;">CDBH3-54/S/C/A-HF</td> <td align="center" style="padding: 5px;">SOT-523</td> </tr> </tbody> </table>		Part No.	Package Type	CDBH3-54/S/C/A-HF	SOT-523						
Part No.	Package Type										
CDBH3-54/S/C/A-HF	SOT-523										
Reason for Discontinuance :											
Due to low demand, the part listed below will be discontinued.											
Alternative Products :											
<table border="1" style="margin: auto; border-collapse: collapse;"> <thead> <tr> <th style="padding: 5px;">EOL p/n.</th> <th style="padding: 5px;">Alternative p/n</th> </tr> </thead> <tbody> <tr> <td align="center" style="padding: 5px;">CDBH3-54-HF</td> <td align="center" style="padding: 5px;">BAT54T-HF</td> </tr> <tr> <td align="center" style="padding: 5px;">CDBH3-54A-HF</td> <td align="center" style="padding: 5px;">BAT54AT-HF</td> </tr> <tr> <td align="center" style="padding: 5px;">CDBH3-54C-HF</td> <td align="center" style="padding: 5px;">BAT54CT-HF</td> </tr> <tr> <td align="center" style="padding: 5px;">CDBH3-54S-HF</td> <td align="center" style="padding: 5px;">BAT54ST-HF</td> </tr> </tbody> </table>		EOL p/n.	Alternative p/n	CDBH3-54-HF	BAT54T-HF	CDBH3-54A-HF	BAT54AT-HF	CDBH3-54C-HF	BAT54CT-HF	CDBH3-54S-HF	BAT54ST-HF
EOL p/n.	Alternative p/n										
CDBH3-54-HF	BAT54T-HF										
CDBH3-54A-HF	BAT54AT-HF										
CDBH3-54C-HF	BAT54CT-HF										
CDBH3-54S-HF	BAT54ST-HF										
Last time buy / order entry : Feb 28, 2022											
Effective Date : Sep 30, 2022											
R&D Dept. Signature :	QA Dept. Signature :										
											