

**PANDUIT**building a smarter,  
unified business foundation

Connect. Manage. Automate.

PCN# 2016-04-26-NK-1 Issue Date: 06May2016

# Product Change Notification

## (Discontinuation of NetKey Fiber Pot & Polish and Opticam Connectors)

**Product Group:** NF - Netkey Copper, Fiber Cable**Distribution:** Global**Related ECN#(s)** N/A**Description of Change:** (Add photos/drawing required where applicable)**Enter part numbers here**

Parts To Obsolete	Replacement Parts
NKFLCSMAQ	FLCSMCXAQY
NKFLCSMBL	FLCSMBLY
NKFLCSMWH	FLCSMC6EIY- Electric Ivory
NKFLCSSWH	NA in WHITE/FLCSSBUY (BU)
NKFSCMAQ	FSCMCXAQ
NKFSCMBL	FSCMBL
NKFSCMPC5BL	FSCMPC5BL
NKFSCMPC5BL-C	FSCMPC5BL-C
NKFSCMPC6EI	FSCMPC6EI
NKFSCMPC6EI-C	FSCMPC6EI-C
NKFSCMWH	FSCMC6EI- Electric Ivory
NKFSCSWH	NA in WHITE/FSCSBU (BU)
NKFSTMABL	FSTMABL
NKFSTMARD	FSTMARD
NKFSTMPC5BL	FSTMPC5BL
NKFSTMPC5BL-C	FSTMPC5BL-C
NKFSTMPC6EI	FSTMPC6EI
NKFSTMPC6EI-C	FSTMPC6EI-C
NKFSTSABU	FSTSABU
NKFLCLIP-L	FLCLIP-L
NKFSCCLIP-L	FSCCLIP-L

**Reason for Change:** The NetKey Opticam and Pot & Polish connector offering is the same as the PanNet versions and there has been very little sales traction on the NetKey versions. Further there has not been a NetKey branded fiber cable offering, Therefore, it has been decided to consolidate on a single loose piece fiber connector and fiber bulk cable offering branded as Panduit.

**Expected Influence on Quality/Reliability/Performance:**

None



building a smarter,  
unified business foundation  
Connect. Manage. Automate.

**Available Replacement/Alternatives:**

Yes

**Part Numbers/ Series/Families Affected:** NKFLCS\*\*\*, NKFSCM\*\*, NKFSCMPC\*\*\*, NKFSCMPC\*\*\*-C, NKFSCSWH, NKFSTMA\*\*, NKFSTMPC\*\*\*, NKFSTMPC\*\*\*-C, NKFSTSABU, NKFLCCLIP-L, NKFSCCLIP-L

Schedule for Change	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2016	05	06
Old product discontinuation date*	2016	08	06

\*Note: After old product discontinuation date, the affected part numbers listed above will continue to be available for sale as long as supplies last. Product may be returned up to 60 days after the product discontinuation date.

<b>ASIA PACIFIC</b>	AUSTRALIA: 1-800 7263848 <a href="mailto:AUS-CustomerService@panduit.com">AUS-CustomerService@panduit.com</a>	CHINA: 800-820-1900 <a href="mailto:CHN-CustomerService@panduit.com">CHN-CustomerService@panduit.com</a>	HONG KONG: 800-965768 <a href="mailto:SGP-customer_service@panduit.com">SGP-customer_service@panduit.com</a>	
	INDIA: 000 800 6501844 (Fixed Line) 000 800 6500369 (Mobile) <a href="mailto:IND-customer_service@panduit.com">IND-customer_service@panduit.com</a>	INDONESIA: 001 803 65 7571 <a href="mailto:SGP-customer_service@panduit.com">SGP-customer_service@panduit.com</a>	JAPAN: +81-3-6863-6000 <a href="mailto:JPN-CS@panduit.com">JPN-CS@panduit.com</a>	
	KOREA: 02-2182-7300 <a href="mailto:KOR-CustomerService@panduit.com">KOR-CustomerService@panduit.com</a>	MALAYSIA: 1800 801435 <a href="mailto:SGP-customer_service@panduit.com">SGP-customer_service@panduit.com</a>	SINGAPORE: 1-800-7263848 <a href="mailto:SGP-CUSTOMER_SERVICE@panduit.com">SGP-CUSTOMER_SERVICE@panduit.com</a>	
	TAIWAN: 0080 165 1487 <a href="mailto:SGP-CUSTOMER_SERVICE@panduit.com">SGP-CUSTOMER_SERVICE@panduit.com</a>	THAILAND: 001-800-65-6385 <a href="mailto:SGP-customer_service@panduit.com">SGP-customer_service@panduit.com</a>		
<b>LATIN AMERICA</b>	BRAZIL: 55+11+36132353 08000562613 (Toll Free) <a href="mailto:BRA-customerservice@panduit.com">BRA-customerservice@panduit.com</a>	MEXICO: +52-33-37776000, X80520 01 800 360 86 00 (Toll Free) <a href="mailto:mex-customerservice@panduit.com">mex-customerservice@panduit.com</a>	OTHER LA COUNTRIES: 708-532-1800 <a href="mailto:TP-CS-INTERNATIONAL@panduit.com">TP-CS-INTERNATIONAL@panduit.com</a>	
<b>NORTH AMERICA</b>	USA & CANADA: 1-800-777-3300 <a href="mailto:cs@panduit.com">cs@panduit.com</a>	<b>EMEA</b>	NUMBER: +44 208 6017219 <a href="mailto:EMEA-sCustomerServices@panduit.com">EMEA-sCustomerServices@panduit.com</a>	

To add a contact or to unsubscribe, please send an e-mail to [PCN@panduit.com](mailto:PCN@panduit.com)