

Product Discontinuation



PD_112_17

| | |
|-----------------------|------------|
| ■ Last Order Date: | 2019-06-30 |
| ■ Last Delivery Date: | 2019-12-31 |

Reason: Ramp down of C5NR5/ C5OPTechnology

Life time can be extended beyond LOD/LDD on request pls feedback until LOD date.

Following conditions will be applicable to extend life time beyond LOD 2019/06/30 / LDD 2019/12/31:

1. NCNR (Non-Cancelable Non-Returnable)
2. Price will be applicable based on quantity commitment and has to be discussed/agreed individually until LOD **Pls contact your Infineon sales for details**
(Extension possible for 2 or 4 and maximum 6years with related price adder)
3. MOQ depends on Product

Please note that there could be technical changes to support the extension beyond PD dates. Product change notifications (PCN) may be necessary.

| DISCONTINUED | | | | NEW (REPLACEMENT) | |
|--------------------|---------------|-------------------|------------|--|----------------|
| Device | Ordering Code | OPN | Package | Device | Package |
| SAB-C161K-LM HA | SP000011584 | C161KLMHABXQMA1 | PG-MQFP-80 | XMC4200/XMC4400 Specific device out of the family to be selected with your local distributor or sales | QFP-100/QFP-64 |
| SAB-C161K-LM HA | SP000011585 | C161KLMHABXUMA1 | PG-MQFP-80 | XMC4200/XMC4400 Specific device out of the family to be selected with your local distributor or sales | QFP-100/QFP-64 |
| SAB-C161O-L25M HA | SP000014268 | C161OL25MHABXUMA1 | PG-MQFP-80 | XMC4200/XMC4400 | QFP-100/QFP-64 |
| SAB-C161O-LM 3V HA | SP000011588 | C161OLM3VHABXUMA1 | PG-MQFP-80 | XMC4200/XMC4400 | QFP-100/QFP-64 |
| SAB-C161O-LM HA | SP000011586 | C161OLMHABXQMA1 | PG-MQFP-80 | XMC4200/XMC4400 | QFP-100/QFP-64 |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_112_17

| | |
|-----------------------|------------|
| ■ Last Order Date: | 2019-06-30 |
| ■ Last Delivery Date: | 2019-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | |
|----------------------|---------------|--------------------|-------------|--|----------------|
| Device | Ordering Code | OPN | Package | Device | Package |
| SAB-C161O-LM HA | SP000011587 | C161OLMHABXUMA1 | PG-MQFP-80 | XMC4200/XMC4400 | QFP-100/QFP-64 |
| SAB-C161PI-L25F CA | SP000014362 | C161PIL25FCABXUMA1 | PG-TQFP-100 | XMC4200/XMC4400 | QFP-100 |
| SAB-C161PI-L25M CA | SP000014367 | C161PIL25MCABXUMA1 | PG-MQFP-100 | XMC4200/XMC4400 | QFP-100 |
| SAB-C161PI-LF 3V CA | SP000014360 | C161PILF3VCABXUMA1 | PG-TQFP-100 | XMC4200/XMC4400 | QFP-100 |
| SAB-C161PI-LF CA | SP000014344 | C161PILFCABXUMA1 | PG-TQFP-100 | XMC4200/XMC4400 | QFP-100 |
| SAB-C161PI-LM 3V CA | SP000014365 | C161PILM3VCABXUMA1 | PG-MQFP-100 | XMC4200/XMC4400 | QFP-100 |
| SAB-C161PI-LM CA | SP000014345 | C161PILMCABXUMA1 | PG-MQFP-100 | XMC4200/XMC4400 | QFP-100 |
| SAB-C161S-L25M AA | SP000014739 | C161SL25MAABXUMA1 | PG-MQFP-80 | XMC4200/XMC4400 | QFP-100/QFP-64 |
| SAB-C161S-LM 3V AA | SP000014946 | C161SLM3VAABXUMA1 | PG-MQFP-80 | XMC4200/XMC4400 | QFP-100/QFP-64 |
| SAB-C164CI-LM 3V CA+ | SP000103494 | C164CILM3VCABXUMA1 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAB-C165-L25F HA | SP000011591 | C165L25FHABFQMA1 | PG-TQFP-100 | XMC4200/XMC4400 | QFP-100 |
| SAB-C165-L25F HA | SP000011592 | C165L25FHABXUMA1 | PG-TQFP-100 | XMC4200/XMC4400 | QFP-100 |
| SAB-C165-L25M HA | SP000011593 | C165L25MHABXQMA1 | PG-MQFP-100 | XMC4200/XMC4400 | QFP-100 |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_112_17

| | |
|-----------------------|------------|
| ■ Last Order Date: | 2019-06-30 |
| ■ Last Delivery Date: | 2019-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | |
|---------------------|---------------|--------------------|-------------|--|---------|
| Device | Ordering Code | OPN | Package | Device | Package |
| SAB-C165-L25M HA | SP000011594 | C165L25MHABXUMA1 | PG-MQFP-100 | XMC4200/XMC4400 | QFP-100 |
| SAB-C165-LF 3V HA | SP000011597 | C165LF3VHABXUMA1 | PG-TQFP-100 | XMC4200/XMC4400 | QFP-100 |
| SAB-C165-LF HA | SP000011595 | C165LFHABXQMA1 | PG-TQFP-100 | XMC4200/XMC4400 | QFP-100 |
| SAB-C165-LF HA | SP000011596 | C165LFHABXUMA1 | PG-TQFP-100 | XMC4200/XMC4400 | QFP-100 |
| SAB-C165-LM 3V HA | SP000011600 | N.A. | PG-MQFP-100 | XMC4200/XMC4400 | QFP-100 |
| SAB-C165-LM HA | SP000011599 | C165LMHABXUMA1 | PG-MQFP-100 | XMC4200/XMC4400 | QFP-100 |
| SAB-C167CR-LM HA+ | SP000103462 | C167CRLMHABXQLA1 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAB-C167CR-LM HA+ | SP000103463 | C167CRLMHABXUMA1 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAB-C167CR-LM HA+ | SP001305110 | C167CRLMHABXUMA2 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAB-C167CR-LM HA+ | SP001691000 | C167CRLMHABXQLA2 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAB-C167CS-L40M CA+ | SP000103468 | C167CSL40MCABXUMA1 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAB-C167CS-L40M CA+ | SP000103471 | C167CSL40MCABXQLA1 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_112_17

| | |
|-----------------------|------------|
| ■ Last Order Date: | 2019-06-30 |
| ■ Last Delivery Date: | 2019-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | |
|---------------------|---------------|--------------------|-------------|--|---------------|
| Device | Ordering Code | OPN | Package | Device | Package |
| SAB-C167CS-L40M CA+ | SP001282748 | C167CSL40MCABXQLA2 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAB-C167CS-L40M CA+ | SP001282752 | C167CSL40MCABXUMA2 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAB-C167CS-LM CA+ | SP000103483 | C167CSLMCABXQLA1 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAB-C167CS-LM CA+ | SP000103484 | C167CSLMCABXUMA1 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAB-C167CS-LM CA+ | SP001282738 | C167CSLMCABXUMA2 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAB-C167CS-LM CA+ | SP001282740 | C167CSLMCABXQLA2 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAB-C167SR-LM HA+ | SP000103456 | C167SRLMHABXQLA1 | PG-MQFP-144 | XMC4500/XMC4700 | QFP-144 |
| SAB-C167SR-LM HA+ | SP000103457 | C167SRLMHABXUMA1 | PG-MQFP-144 | XMC4500/XMC4700 | QFP-144 |
| SAB-C167SR-LM HA+ | SP001305112 | C167SRLMHABXUMA2 | PG-MQFP-144 | XMC4500/XMC4700 | QFP-144 |
| SAB-C167SR-LM HA+ | SP001691004 | C167SRLMHABXQLA2 | PG-MQFP-144 | XMC4500/XMC4700 | QFP-144 |
| SAB-C504-2EM CC | SP000362463 | C5042EMCCBXQMA1 | PG-MQFP-44 | XMC1400 | QFN-48/QFN-40 |
| SAB-C505CA-4EM CA | SP000106391 | C505CA4EMCABXQMA1 | PG-MQFP-44 | XMC1400 | QFN-48/QFN-40 |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_112_17

| | |
|-----------------------|------------|
| ■ Last Order Date: | 2019-06-30 |
| ■ Last Delivery Date: | 2019-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | |
|---------------------|---------------|--------------------|-------------|--|----------------|
| Device | Ordering Code | OPN | Package | Device | Package |
| SAB-C505CA-4EM CA | SP000106392 | C505CA4EMCABXUMA1 | PG-MQFP-44 | XMC1400 | QFN-48/QFN-40 |
| SAF-C161CS-LF CA | SP001607262 | C161CSLFCAFXUMA2 | PG-TQFP-128 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAF-C161CS-LF CA | SP001619672 | C161CSLFCAFXQMA2 | PG-TQFP-128 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAF-C161K-LM 3V HA | SP000011621 | C161KLM3VHAFXUMA1 | PG-MQFP-80 | XMC4200/XMC4400 | QFP-100/QFP-64 |
| SAF-C161K-LM HA | SP000011620 | C161KLMHAFXQMA1 | PG-MQFP-80 | XMC4200/XMC4400 | QFP-100/QFP-64 |
| SAF-C161O-LM 3V HA | SP000011624 | C161OLM3VHAFXUMA1 | PG-MQFP-80 | XMC4200/XMC4400 | QFP-100/QFP-64 |
| SAF-C161O-LM HA | SP000011622 | C161OLMHAFXQMA1 | PG-MQFP-80 | XMC4200/XMC4400 | QFP-100/QFP-64 |
| SAF-C161O-LM HA | SP000011623 | C161OLMHAFXUMA1 | PG-MQFP-80 | XMC4200/XMC4400 | QFP-100/QFP-64 |
| SAF-C161PI-L25F CA | SP000014363 | C161PIL25FCAFXUMA1 | PG-TQFP-100 | XMC4200/XMC4400 | QFP-100 |
| SAF-C161PI-L25M CA | SP000014368 | C161PIL25MCAFXUMA1 | PG-MQFP-100 | XMC4200/XMC4400 | QFP-100 |
| SAF-C161PI-LF 3V CA | SP000014361 | C161PILF3VCAFXUMA1 | PG-TQFP-100 | XMC4200/XMC4400 | QFP-100 |
| SAF-C161PI-LF CA | SP000014359 | C161PILFCAFXUMA1 | PG-TQFP-100 | XMC4200/XMC4400 | QFP-100 |
| SAF-C161PI-LM 3V CA | SP000014366 | C161PILM3VCAFXUMA1 | PG-MQFP-100 | XMC4200/XMC4400 | QFP-100 |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_112_17

| | |
|-----------------------|------------|
| ■ Last Order Date: | 2019-06-30 |
| ■ Last Delivery Date: | 2019-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | |
|------------------------|---------------|----------------------|-------------|--|----------------|
| Device | Ordering Code | OPN | Package | Device | Package |
| SAF-C161PI-LM CA | SP000014364 | C161PILMCAFXUMA1 | PG-MQFP-100 | XMC4200/XMC4400 | QFP-100 |
| SAF-C161S-L25M AA | SP000014947 | C161SL25MAAFXUMA1 | PG-MQFP-80 | XMC4200/XMC4400 | QFP-100/QFP-64 |
| SAF-C161S-LM 3V AA | SP000014948 | C161SLM3VAAAFXUMA1 | PG-MQFP-80 | XMC4200/XMC4400 | QFP-100/QFP-64 |
| SAF-C164CI-8E25M DB | SP000104053 | C164CI8E25MDBFXQMA1 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAF-C164CI-8E25M DB | SP000104054 | C164CI8E25MDBFXUMA1 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAF-C164CI-8EM CB | SP000103498 | C164CI8EMCBFXQMA1 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAF-C164CI-8EM CB | SP000103499 | C164CI8EMCBFXUMA1 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAF-C164CI-8EM DB | SP000104055 | C164CI8EMDBFXQMA1 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAF-C164CI-8RM CA+ | SP000950576 | C164CI8RMCAFXQMA1 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAF-C164CI-8RM CA+ | SP001002936 | C164CI8RMCAFXUMA1 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAF-C164CI-LM CA+ | SP000103495 | C164CILMCAFXUMA1 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAF-C164SL-8R25M-4 CA+ | SP000300942 | C164SL8R25M4CAFXUMA3 | PG-MQFP-80 | XMC4200/XMC4400 | QFP-100/QFP-64 |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_112_17

| | |
|-----------------------|------------|
| ■ Last Order Date: | 2019-06-30 |
| ■ Last Delivery Date: | 2019-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | |
|-------------------|---------------|------------------|-------------|--|---------|
| Device | Ordering Code | OPN | Package | Device | Package |
| SAF-C165-L25F HA | SP000012870 | C165L25FHAFXUMA1 | PG-TQFP-100 | XMC4200/XMC4400 | QFP-100 |
| SAF-C165-L25M HA | SP000011629 | C165L25MHAFXQMA1 | PG-MQFP-100 | XMC4200/XMC4400 | QFP-100 |
| SAF-C165-L25M HA | SP000011630 | C165L25MHAFXUMA1 | PG-MQFP-100 | XMC4200/XMC4400 | QFP-100 |
| SAF-C165-LF 3V HA | SP000011632 | C165LF3VHAFXUMA1 | PG-TQFP-100 | XMC4200/XMC4400 | QFP-100 |
| SAF-C165-LF HA | SP000011631 | C165LFHAFXUMA1 | PG-TQFP-100 | XMC4200/XMC4400 | QFP-100 |
| SAF-C165-LM 3V HA | SP000011635 | C165LM3VHAFXUMA1 | PG-MQFP-100 | XMC4200/XMC4400 | QFP-100 |
| SAF-C165-LM HA | SP000011633 | C165LMHAFXQMA1 | PG-MQFP-100 | XMC4200/XMC4400 | QFP-100 |
| SAF-C165-LM HA | SP000011634 | C165LMHAFXUMA1 | PG-MQFP-100 | XMC4200/XMC4400 | QFP-100 |
| SAF-C167CR-LM HA+ | SP000103464 | C167CRLMHAFXQLA1 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAF-C167CR-LM HA+ | SP000103465 | C167CRLMHAFXUMA1 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAF-C167CR-LM HA+ | SP001259646 | C167CRLMHAFXUMA2 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAF-C167CR-LM HA+ | SP001282722 | C167CRLMHAFXQLA2 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_112_17

| | |
|-----------------------|------------|
| ■ Last Order Date: | 2019-06-30 |
| ■ Last Delivery Date: | 2019-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | |
|------------------------|---------------|----------------------|-------------|--|---------------|
| Device | Ordering Code | OPN | Package | Device | Package |
| SAF-C167CS-L16M 3V CA+ | SP000103469 | C167CSL16M3VCAFXQLA1 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAF-C167CS-L16M 3V CA+ | SP000103470 | C167CSL16M3VCAFXUMA1 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAF-C167CS-L16M 3V CA+ | SP001305114 | C167CSL16M3VCAFXUMA2 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAF-C167CS-L16M 3V CA+ | SP001691006 | C167CSL16M3VCAFXQLA2 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAF-C167CS-L33M CA+ | SP000103485 | C167CSL33MCAFXQLA1 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAF-C167CS-L33M CA+ | SP000103486 | C167CSL33MCAFXUMA1 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAF-C167CS-L33M CA+ | SP001282742 | C167CSL33MCAFXUMA2 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAF-C167CS-LM CA+ | SP000103487 | C167CSLMCAFXQLA1 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAF-C167CS-LM CA+ | SP000103488 | C167CSLMCAFXUMA1 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAF-C167CS-LM CA+ | SP001282732 | C167CSLMCAFXQLA2 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAF-C505CA-4EM CA | SP000106394 | C505CA4EMCAFXQMA1 | PG-MQFP-44 | XMC1400 | QFN-48/QFN-40 |
| SAF-C505CA-4EM CA | SP000106395 | C505CA4EMCAFXUMA1 | PG-MQFP-44 | XMC1400 | QFN-48/QFN-40 |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_112_17

| | |
|-----------------------|------------|
| ■ Last Order Date: | 2019-06-30 |
| ■ Last Delivery Date: | 2019-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | |
|----------------------|---------------|---------------------|------------|--|-----------------|
| Device | Ordering Code | OPN | Package | Device | Package |
| SAF-C505CA-4RM CA | SP000256151 | C505CA4RMCAFXUMA5 | PG-MQFP-44 | XMC1400 | QFN-48/QFN-40 |
| SAF-C505CA-4RM CA | SP000401504 | C505CA4RMCAFXUMA7 | PG-MQFP-44 | XMC1400 | QFN-48/QFN-40 |
| SAF-C505CA-LM CA | SP000106390 | C505CALMCAFXUMA1 | PG-MQFP-44 | XMC1400 | QFN-48/QFN-40 |
| SAF-C505CA-LM CA | SP000106669 | C505CALMCAFXQMA1 | PG-MQFP-44 | XMC1400 | QFN-48/QFN-40 |
| SAF-C505L-4EM CC | SP000924788 | C505L4EMCCFXUMA1 | PG-MQFP-80 | XMC1400/XMC4200/XMC4400 | QFP-64/ QFP-100 |
| SAF-C505L-4EM CC | SP000969384 | C505L4EMCCFXQMA1 | PG-MQFP-80 | XMC1400/XMC4200/XMC4400 | QFP-64/ QFP-100 |
| SAF-C515C-8EM CA | SP000106398 | C515C8EMCAFXQMA1 | PG-MQFP-80 | XMC1400/XMC4200/XMC4400 | QFP-64/ QFP-100 |
| SAF-C515C-8EM CA | SP000106399 | C515C8EMCAFXUMA1 | PG-MQFP-80 | XMC1400/XMC4200/XMC4400 | QFP-64/ QFP-100 |
| SAF-C515C-8EM CA | SP000106400 | C515C8EMCAFXUMA2 | PG-MQFP-80 | XMC1400/XMC4200/XMC4400 | QFP-64/ QFP-100 |
| SAH-C164SL-6RM CA+ | SP000602228 | C164SL6RMCAHXUMA3 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAH-C164SL-6RM CA+ | SP000602234 | C164SL6RMCAHXUMA4 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAH-C164SL-8R25M CA+ | SP000363501 | C164SL8R25MCAHXUMA1 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAH-C164SL-8R25M CA+ | SP000845382 | C164SL8R25MCAHXUMA7 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_112_17

| | |
|-----------------------|------------|
| ■ Last Order Date: | 2019-06-30 |
| ■ Last Delivery Date: | 2019-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | |
|-----------------------|---------------|-----------------------|------------|--|----------------|
| Device | Ordering Code | OPN | Package | Device | Package |
| SAH-C164SL-8R25M CA+ | SP000989768 | C164SL8R25MCAHXUMA8 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAH-C164SL-8RM CA+ | SP000602230 | C164SL8RMCAHXUMA2 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAH-C164SL-8RM CA+ | SP000602232 | C164SL8RMCAHXUMA3 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164CI-8E25M DB | SP000104057 | C164CI8E25MDBKXQMA1 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164CI-8E25M DB | SP000104058 | C164CI8E25MDBKXUMA1 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164CI-8EM CB | SP000103500 | C164CI8EMCBKXQMA1 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164CI-8EM CB | SP000103501 | C164CI8EMCBKXUMA1 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164CI-8EM DB | SP000104059 | C164CI8EMDBKXQMA1 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164CI-8EM DB | SP000104060 | C164CI8EMDBKXUMA1 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164CI-8RM B60288 | SP000241732 | C164CI8RMB60288KNUMA1 | P-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164CI-8RM B60288 | SP000275333 | C164CI8RMB60288KNUMA2 | P-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164CI-8RM CA+ | SP000372730 | C164CI8RMCAKXUMA2 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_112_17

| | |
|-----------------------|------------|
| ■ Last Order Date: | 2019-06-30 |
| ■ Last Delivery Date: | 2019-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | |
|---------------------|---------------|--------------------|------------|--|----------------|
| Device | Ordering Code | OPN | Package | Device | Package |
| SAK-C164CI-8RM CA+ | SP000472716 | C164CI8RMCAKXUMA3 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164CI-8RM CA+ | SP000474956 | C164CI8RMCAKXUMA4 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164CI-8RM CA+ | SP000476990 | C164CI8RMCAKXUMA5 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164CI-8RM CA+ | SP000477026 | C164CI8RMCAKXUMA6 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164CI-8RM CA+ | SP000654628 | C164CI8RMCAKXUMA8 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164CI-8RM CA+ | SP000846358 | C164CI8RMCAKXUMA9 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164CI-8RM CA+ | SP000915048 | C164CI8RMCAKXUMB1 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164CI-8RM CA+ | SP000915050 | C164CI8RMCAKXUMA1 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164CI-8RM CA+ | SP000920910 | C164CI8RMCAKXUMB2 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164CI-8RM CA+ | SP001300832 | C164CI8RMCAKXUMB3 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164CI-L25M CA+ | SP000103496 | C164CIL25MCAKXUMA1 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164CI-LM CA+ | SP000103497 | C164CILMCAKXUMA1 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_112_17

| | |
|-----------------------|------------|
| ■ Last Order Date: | 2019-06-30 |
| ■ Last Delivery Date: | 2019-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | |
|--------------------|---------------|-------------------|------------|--|----------------|
| Device | Ordering Code | OPN | Package | Device | Package |
| SAK-C164CL-6RM CA+ | SP000247998 | C164CL6RMCAKXUMA1 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164CL-6RM CA+ | SP000248003 | C164CL6RMCAKXUMA2 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164CL-6RM CA+ | SP000374347 | C164CL6RMCAKXUMA3 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164CL-8RM CA+ | SP000311501 | C164CL8RMCAKXQMA1 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164CL-8RM CA+ | SP000311527 | C164CL8RMCAKXQMA2 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164CL-8RM CA+ | SP000316705 | C164CL8RMCAKXQMA3 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164CL-8RM CA+ | SP000361243 | C164CL8RMCAKXQMA4 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164CL-8RM CA+ | SP000364404 | C164CL8RMCAKXUMA1 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164CL-8RM CA+ | SP000374348 | C164CL8RMCAKXUMA2 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164CL-8RM CA+ | SP000404704 | C164CL8RMCAKXQMA5 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164CL-8RM CA+ | SP000453980 | C164CL8RMCAKXQMA6 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164CL-8RM CA+ | SP000632272 | C164CL8RMCAKXUMA3 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_112_17

| | |
|-----------------------|------------|
| ■ Last Order Date: | 2019-06-30 |
| ■ Last Delivery Date: | 2019-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | |
|--------------------|---------------|-------------------|------------|--|----------------|
| Device | Ordering Code | OPN | Package | Device | Package |
| SAK-C164CL-8RM CA+ | SP000659234 | C164CL8RMCAKXQMA9 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164CL-8RM CA+ | SP000676914 | C164CL8RMCAKXQMB1 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164CL-8RM CA+ | SP000857384 | C164CL8RMCAKXQMB2 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164CL-8RM CA+ | SP000859024 | C164CL8RMCAKXQMB3 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164CL-8RM CA+ | SP000978840 | C164CL8RMCAKXQMB4 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164CL-8RM CA+ | SP000990742 | C164CL8RMCAKXQMB6 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164CL-8RM CA+ | SP000990744 | C164CL8RMCAKXQMB5 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164SL-6RM CA+ | SP000364405 | C164SL6RMCAKXUMA1 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164SL-6RM CA+ | SP000374349 | C164SL6RMCAKXUMA2 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164SL-6RM CA+ | SP000374350 | C164SL6RMCAKXUMA3 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164SL-6RM CA+ | SP000610906 | C164SL6RMCAKXUMA4 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164SL-6RM CA+ | SP000736484 | C164SL6RMCAKXUMA5 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_112_17

| | |
|-----------------------|------------|
| ■ Last Order Date: | 2019-06-30 |
| ■ Last Delivery Date: | 2019-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | |
|---------------------|---------------|--------------------|-------------|--|----------------|
| Device | Ordering Code | OPN | Package | Device | Package |
| SAK-C164SL-6RM CA+ | SP000797634 | C164SL6RMCAKXUMA6 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164SL-6RM CA+ | SP000835374 | C164SL6RMCAKXUMA7 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164SL-8RM CA+ | SP000361242 | C164SL8RMCAKXQMA1 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164SL-8RM CA+ | SP000474948 | C164SL8RMCAKXUMA1 | PG-MQFP-80 | XMC4200/XMC4400 XC226xx/XC236xx/XC276xx | QFP-100/QFP-64 |
| SAK-C164SM-4RF CA | SP000419318 | C164SM4RFCAKXUMA2 | PG-LQFP-64 | XMC4200/XMC4400 XC223xx/XC233xx/XC273xx | QFP-64 |
| SAK-C164SM-4RF CA | SP000540710 | C164SM4RFCAKXUMA3 | PG-LQFP-64 | XMC4200/XMC4400 XC223xx/XC233xx/XC273xx | QFP-64 |
| SAK-C167CR-L33M HA+ | SP000103460 | C167CRL33MHAKXQLA1 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAK-C167CR-L33M HA+ | SP000103461 | C167CRL33MHAKXUMA1 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAK-C167CR-L33M HA+ | SP001282728 | C167CRL33MHAKXQLA2 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAK-C167CR-L33M HA+ | SP001282730 | C167CRL33MHAKXUMA2 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAK-C167CR-LM HA+ | SP000103466 | C167CRLMHAKXQLA1 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAK-C167CR-LM HA+ | SP000103467 | C167CRLMHAKXUMA1 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_112_17

| | |
|-----------------------|------------|
| ■ Last Order Date: | 2019-06-30 |
| ■ Last Delivery Date: | 2019-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | |
|---------------------|---------------|--------------------|-------------|--|---------|
| Device | Ordering Code | OPN | Package | Device | Package |
| SAK-C167CR-LM HA+ | SP001259672 | C167CRLMHAKXUMA2 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAK-C167CS-L33M CA+ | SP000103489 | C167CSL33MCAKXUMA1 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAK-C167CS-L33M CA+ | SP001282736 | C167CSL33MCAKXUMA2 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAK-C167CS-L40M CA+ | SP000103490 | C167CSL40MCAKXQLA1 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAK-C167CS-L40M CA+ | SP000103491 | C167CSL40MCAKXUMA1 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAK-C167CS-L40M CA+ | SP001259676 | C167CSL40MCAKXUMA2 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAK-C167CS-L40M CA+ | SP001282750 | C167CSL40MCAKXQLA2 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAK-C167CS-LM CA+ | SP000103492 | C167CSLMCAKXQLA1 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAK-C167CS-LM CA+ | SP000103493 | C167CSLMCAKXUMA1 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAK-C167CS-LM CA+ | SP001254228 | C167CSLMCAKXUMA3 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAK-C167CS-LM CA+ | SP001259680 | C167CSLMCAKXUMA2 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAK-C167SR-LM HA+ | SP000103458 | C167SRLMHAKXQLA1 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_112_17

| | |
|-----------------------|------------|
| ■ Last Order Date: | 2019-06-30 |
| ■ Last Delivery Date: | 2019-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | |
|-------------------|---------------|-------------------|-------------|--|---------------|
| Device | Ordering Code | OPN | Package | Device | Package |
| SAK-C167SR-LM HA+ | SP000103459 | C167SRLMHAKXUMA1 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAK-C167SR-LM HA+ | SP001259682 | C167SRLMHAKXUMA2 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAK-C167SR-LM HA+ | SP001282726 | C167SRLMHAKXQLA2 | PG-MQFP-144 | XMC4500/XMC4700 XC228xx/XC238xx/XC278xx | QFP-144 |
| SAK-C504-2E24M CC | SP000870278 | C5042E24MCCKXUMA1 | PG-MQFP-44 | XMC1400 | QFN-48/QFN-40 |
| SAK-C505CA-2RM CA | SP000478842 | C505CA2RMCAKXUMA1 | PG-MQFP-44 | XMC1400 | QFN-48/QFN-40 |
| SAK-C505CA-2RM CA | SP000930282 | C505CA2RMCAKXUMA2 | PG-MQFP-44 | XMC1400 | QFN-48/QFN-40 |
| SAK-C505CA-4EM CA | SP000106396 | C505CA4EMCAKXQMA1 | PG-MQFP-44 | XMC1400 | QFN-48/QFN-40 |
| SAK-C505CA-4EM CA | SP000106397 | C505CA4EMCAKXUMA1 | PG-MQFP-44 | XMC1400 | QFN-48/QFN-40 |
| SAK-C505CA-4EM CA | SP000107542 | C505CA4EMCAKXUMA2 | PG-MQFP-44 | XMC1400 | QFN-48/QFN-40 |
| SAK-C505CA-4RM CA | SP000478832 | C505CA4RMCAKXUMA2 | PG-MQFP-44 | XMC1400 | QFN-48/QFN-40 |

If you have any questions, please do not hesitate to contact your Infineon sales for details

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!