

PRODUCT CHANGE NOTIFICATION

Product Category PRE-CONFIGURED DATA CENTER **20230123-1**

Product Group CONVERGED INFRASTRUCTURE

ISSUE DATE: 23-Jan-23

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

Obsoleting Pre-configured Non-Standard/Configure to order Net Access Style Cabinets and accessories

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[See Tab - Part Numbers](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2022	1	1
Old product discontinuation date*	2022	3	29

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(s)	Compatibility Type
--------------------------------	---------------------------

ES8822W003Q	No Replacement
S8129WS-0177B	No Replacement
ES8822W004M	No Replacement
CQSSAPPROTO4	No Replacement
S8522BN-0028	No Replacement
S8522BV-0181	No Replacement
S8121WS-0177D	No Replacement
ES8222B001T	No Replacement
N8522BV-0182	No Replacement
S8121WS-0177B	No Replacement
N8522BS-0176I	No Replacement
ES8522B003C	No Replacement
S7521WV-0165C	No Replacement
S8522BS-0189	No Replacement
N8522BS-0176K	No Replacement
N8522BC-0087D2	No Replacement
S8129WS-0177C	No Replacement
N8522BS-0085	No Replacement
N8522GV-0165A	No Replacement
N8522BS-0202C	No Replacement
N8522BS-0202A	No Replacement
N8522BS-0190	No Replacement
N8522BS-0202B	No Replacement
N8522BS-0202G	No Replacement
N8522BS-0176M	No Replacement
S8522BS-0202B	No Replacement
S8522BS-0202D	No Replacement
S8121WS-0177C	No Replacement
N8522BS-0176F	No Replacement
N8522BS-0176E	No Replacement
N8522BS-0176D	No Replacement
N8522BS-0176C	No Replacement
N8522BS-0176B	No Replacement
N8522BS-0176A	No Replacement
N8522BS-0202H	No Replacement
S8522BS-0176D	No Replacement
S8522BS-0176C	No Replacement
S8522BS-0176B	No Replacement
S8522BS-0176A	No Replacement
C8822WS-0216	No Replacement
S8522WS-0076	No Replacement
C8822WS-0217	No Replacement
S8522WV-0077	No Replacement
NAKIT2.0G5-B	No Replacement
N8522BS-0176J	No Replacement
N8522BS-0176L	No Replacement

C8522WS-0025	No Replacement
ED7222B002Z	No Replacement
ED7222B0029	No Replacement
N1522GV-0165B	No Replacement
N8522BS-0176G	No Replacement
N8522BS-0176H	No Replacement
N8522WV-0079	No Replacement
N8522WV-0206	No Replacement
N8529BS-0085	No Replacement
N8529GV-0165A	No Replacement
S81SHDW-SZ03	No Replacement
S8222WX-0186	No Replacement
S8521WS-0024C	No Replacement
S8521WSE	No Replacement
S8522BS-0176E	No Replacement
S8522BS-0176F	No Replacement
S8522WV-0205	No Replacement
SN81SDW-SZ03	No Replacement
SNZ85SDB02	No Replacement