

PRODUCT CHANGE NOTIFICATION

Product Category AUDIO VISUAL 20220404-1

Product Group ROAR

ISSUE DATE: 4-Apr-22

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

The following RCA modules are being discontinued due to shifting needs of the AV market space.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*	2022	7	3

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(s)
NKRSMBIWY
NKRSMBWHY
NKRSMRBLY
NKRSMREIY
NKRSMRIGY
NKRSMRIWY
NKRSMRWHY
NKRSMWBLY
NKRSMWEIY
NKRSMWIWY
NKRSMWWHY
NKRSMYBLY
NKRSMYIWY
NKRSMYWHY
NKRSMBBLY
NKRSMBEIY
NKRSMBIGY
NKRSMWIGY