



CUSTOMER OPERATIONS
 160 RIO ROBLES
 SAN JOSE, CA 95134

PDN #: M000987N

DATE: 08-Apr-2020

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	806-0447-30+	N/A	07-Jul-2020	05-Oct-2020	Part can no longer be manufactured
Discontinuance	806-0447-30+T	N/A	07-Jul-2020	05-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX2142ETM/V+	N/A	07-Jul-2020	05-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX2142ETM/V+T	N/A	07-Jul-2020	05-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX4600EWE+T	N/A	07-Jul-2020	05-Oct-2020	Part can no longer be manufactured
Discontinuance	MAX6023EBT50+T	N/A	07-Jul-2020	05-Oct-2020	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 09-May-2020