

Attn.: _____

HIROSE ELECTRIC CO., LTD.
5-23, OSAKI 5-CHOME, SHINAGAWA-KU, TOKYO, JAPAN

Product Change Notification

We are writing today to inform you that we will make some changes as shown in the subject for the reason described below.

We will announce them in advance.

1	Products affected	Please see the attached sheet.
2	Replacement product	Please be advised that we have no plan to offer replacement product.
3	Classification of change	Discontinued sale
4	Reason for change	• Aging of equipment • The demand for the target products is extremely decreasing and it is difficult to secure stable supply.
5	Date of final reception of orders for the current product	April 30, 2020
6	Date of final shipment of the current product	April 30, 2021
7	Date of your acknowledgement	By October 31, 2019

We kindly request that you inform Hirose business representative of your acknowledgement by the aforesaid date.

In the absence of a response by this date, please be advised that replacement product that described above will be delivered.

If you should have any questions, please feel free to contact a Hirose business representative.

Your understanding and cooperation are highly appreciated.

■Product List Business 430-19007_Optical Connector_Discontinued Sale

No	Current product		Replacement product	
	Product code	Product name	Product code	Product name
1	703-0065-2-00	SMPO スプリングE		
2	703-0066-5-00	SMPO-CAP		
3	703-0072-8-00	FIBER-SD-BODY-B		
4	703-0073-0-00	FIBER-S-BODY		
5	704-0516-6-00	HSCF-2SR-S2		
6	704-0547-0-00	HSC-PH2-J6		
7	707-0002-8-40	HRPI-H4-HA-B(40)		
8	707-0009-7-40	HRPI-A-T2(40)		
9	710-0015-2-40	HMUB-L2PA-1(40)		
10	710-0015-2-50	HMUB-L2PA-1(50)		
11	710-0017-8-40	HMUB-L2HA-1(40)		
12	710-0018-0-40	HMUB-L2HB-1(40)		
13	710-0060-7-40	HMUB-DJ-1(40)		
14	710-0075-4-00	HMUB-TP-1		
15	710-0086-0-00	HMUB-L2PA-CAP		
16	710-0086-0-40	HMUB-L2PA-CAP(40)		
17	710-0087-3-40	HMUB-L8PA-CAP(40)		
18	710-0088-6-40	HMUB-L2HA-CAP(40)		
19	710-0110-3-40	HMUB-L2HA-2(40)		
20	710-0002-0-61	HMUA-2P2-H2(61)		
21	821-0001-0-40	HSC-TM-R1(40)		
22	822-0001-6-40	H07-AP-P1(40)		
23	822-0001-6-41	H07-AP-P1(41)		
24	822-0003-1-60	H07-CP-EP1(60)		
25	822-0003-1-61	H07-CP-EP1(61)		
26	822-0004-4-40	H07-CP-F0235(40)		
27	822-0006-0-40	H07-CP-F0230(40)		
28	822-0014-8-60	H07-CP-P1(F0235)(60)		
29	822-0014-8-61	H07-CP-P1(F0235)(61)		
30	822-0015-0-60	H07-CP-P1(F0230)(60)		
31	822-0015-0-61	H07-CP-P1(F0230)(61)		
32	822-0015-0-62	H07-CP-P1(F0230)(62)		
33	822-0016-3-60	H07-CP-EP1(F0235)(60)		
34	822-0016-3-61	H07-CP-EP1(F0235)(61)		
35	822-0017-6-60	H07-CP-EP1(F0230)(60)		
36	822-0017-6-61	H07-CP-EP1(F0230)(61)		
37	822-0018-9-40	H07-CP-F0300(40)		
38	822-0019-1-60	H07-CP-P1(F0300)(60)		
39	822-0019-1-61	H07-CP-P1(F0300)(61)		
40	822-0020-0-60	H07-CP-P1(F1090)(60)		
41	822-0020-0-61	H07-CP-P1(F1090)(61)		
42	822-0021-3-60	H07-CP-EP1(F0300)(60)		
43	822-0021-3-61	H07-CP-EP1(F0300)(61)		
44	822-0026-7-40	H07-CP-A2(40)		
45	822-0026-7-41	H07-CP-A2(41)		
46	822-0027-0-60	H07-CP-P2(F0230)(60)		
47	822-1102-9-31	H07-P22-F2NCFA-10M(31)		
48	822-1102-9-32	H07-P22-F2NCFA-15M(32)		
49	822-1102-9-33	H07-P22-F2NCFA-20M(33)		
50	822-1102-9-34	H07-P22-F2NCFA-30M(34)		
51	822-1102-9-35	H07-P22-F2NCFA-50M(35)		
52	822-1102-9-36	H07-P22-F2NCFA-35M(36)		
53	822-1102-9-37	H07-P22-F2NCFA-70M(37)		
54	822-1102-9-80	H07-P22-F2NCFA-80M(80)		
55	822-1102-9-81	H07-P22-F2NCFA-1M(81)		
56	822-1102-9-82	H07-P22-F2NCFA-2M(82)		
57	822-1102-9-83	H07-P22-F2NCFA-3M(83)		
58	822-1102-9-84	H07-P22-F2NCFA-5M(84)		
59	822-1102-9-85	H07-P22-F2NCFA-7M(85)		
60	822-1102-9-86	H07-P22-F2NCFA-10M(86)		

Please be advised that we have no plan to offer replacement product.

No	Current product		Replacement product	
	Product code	Product name	Product code	Product name
61	822-1102-9-87	H07-P22-F2NCFA-13M(87)		
62	822-1102-9-88	H07-P22-F2NCFA-15M(88)		
63	822-1102-9-89	H07-P22-F2NCFA-20M(89)		
64	822-1102-9-90	H07-P22-F2NCFA-30M(90)		
65	822-1102-9-91	H07-P22-F2NCFA-50M(91)		
66	822-1102-9-92	H07-P22-F2NCFA-2.4M(92)		
67	822-1102-9-93	H07-P22-F2NCFA-2.6M(93)		
68	822-1102-9-94	H07-P22-F2NCFA-1M(94)		
69	822-1102-9-95	H07-P22-F2NCFA-2M(95)		
70	822-1102-9-96	H07-P22-F2NCFA-3M(96)		
71	822-1102-9-97	H07-P22-F2NCFA-5M(97)		
72	822-1102-9-98	H07-P22-F2NCFA-7M(98)		
73	822-1103-1-61	H07-P22-F2NPFA-5M(61)		
74	822-1103-1-62	H07-P22-F2NPFA-7M(62)		
75	822-1103-1-63	H07-P22-F2NPFA-20M(63)		
76	822-1107-2-63	H07-P22-F2N5-3M(63)		
77	822-1107-2-64	H07-P22-F2N5-4M(64)		
78	822-2001-7-43	H07-P22-F2V2-3M(43)		
79	822-2101-1-41	H07-P22-F2VCFA-1M(41)		
80	822-2101-1-42	H07-P22-F2VCFA-2M(42)		
81	822-2101-1-43	H07-P22-F2VCFA-3M(43)		
82	822-2101-1-44	H07-P22-F2VCFA-5M(44)		
83	822-2101-1-45	H07-P22-F2VCFA-7M(45)		
84	822-2101-1-46	H07-P22-F2VCFA-10M(46)		
85	822-2101-1-49	H07-P22-F2VCFA-0.33M(49)		
86	822-2101-1-50	H07-P22-F2VCFA-0.5M(50)		
87	822-2101-1-55	H07-P22-F2VCFA-1.5M(55)		
88	822-2101-1-56	H07-P22-F2VCFA-0.3M(56)		
89	822-2101-1-57	H07-P22-F2VCFA-0.5M(57)		
90	822-2101-1-58	H07-P22-F2VCFA-1M(58)		
91	822-2101-1-59	H07-P22-F2VCFA-2M(59)		
92	822-2101-1-60	H07-P22-F2VCFA-3M(60)		
93	822-2101-1-70	H07-P22-F2VCFA-5M(70)		
94	822-2101-1-79	H07-P22-F2VCFA-7M(79)		
95	822-2101-1-80	H07-P22-F2VCFA-10M(80)		
96	822-2101-1-89	H07-P22-F2VCFA-15M(89)		
97	822-2101-1-90	H07-P22-F2VCFA-20M(90)		
98	822-2101-1-91	H07-P22-F2VCFA-0.28M(91)		
99	822-2101-1-92	H07-P22-F2VCFA-0.43M(92)		
100	822-2102-4-40	H07-P22-F2VCFA-0.15M(40)		
101	822-2102-4-41	H07-P22-F2VCFA-0.18M(41)		
102	822-2102-4-43	H07-P22-F2VCFA-0.22M(43)		

Please be advised that we have no plan to offer replacement product.

Acknowledgement

(Customer → Hirose Electric business representative)

Product Change Notification
Request for Your Acknowledgement

We acknowledge the changes and schedule of this notification.

Customer's name: _____

Acknowledgement stamp (or signature): _____

HIROSE ELECTRIC CO., LTD.

(Cut on this line)

Document Receipt

(Customer → Hirose Electric business representative)

Product Change Notification
Request for Your Acknowledgement

We received the document concerning the above.

Customer's name: _____

Acknowledgment stamp (or signature): _____

HIROSE ELECTRIC CO., LTD.