



# Product Change Notification

## TE Connectivity

Product Change Notification: P-15-011614

PCN Date: 30-APR-15

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

**General Product Description:**

Compound Reformulations and Process Transfers of US-Made BST

**Description of Changes**

One of the components used in manufacturing several of our heavy duty tubing products has been made obsolete by the supplier. To continue to service our valued customers, we are announcing that TE Connectivity will be qualifying a new supplier of the ingredient for compounds used to manufacture these products. The new ingredient is chemically equivalent to the current ingredient. The affected products will continue to meet the AMS-DTL-23053/15, American Bureau of Shipping and Lloyd's Register of Shipping standards along with TE's RW-2017, RW-2011, and RW-2016 specifications. The compound formulation changes along with processing transfers within the Menlo Park, CA manufacturing site (between buildings and equipment) will take effect by July 1, 2015. TE plans to conduct running changes for the reformulation.

Other attachments:

[PCN Bulletin - Compound Reformulations and Process Transfers of US-Made BSTS- FR, SST-FR and XFFR Tubing Products](#)

**Reason for Changes:**

Part status change. TE Connectivity believes these changes will not affect the form, fit or function of the products. TE also recommends that our customers conduct their own evaluation of these products in the specific applications where they are used. Samples and qualification reports will be available to customers upon request through TE's sales channels starting May 1, 2015.

**Estimated Dates:**

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	01-JUL-2015
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">CB5004-000</a>	NO			"BSTS-04X4", "3-1899225-1"			
<a href="#">CB5005-000</a>	NO						
<a href="#">CB5015-000</a>	NO			"1899279-5", "BSTS-07X4"			
<a href="#">CB5018-000</a>	NO			"BSTS-07X4FR"			
<a href="#">CB5036-000</a>	NO						
<a href="#">CB5043-000</a>	NO			"BSTS-15X4", "3-1899213-5"			
<a href="#">CB5045-000</a>	NO						
<a href="#">CB5052-000</a>	NO			"6-1899211-8", "BSTS-17X4"			
<a href="#">CB5060-000</a>	NO						
<a href="#">CB5062-000</a>	NO						
<a href="#">CB5309-000</a>	NO						
<a href="#">CB5316-000</a>	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">CB5330-000</a>	NO						
<a href="#">CB5334-000</a>	NO			"3-1899241-6", "SST-48-07/FR/97"			
<a href="#">CB5346-000</a>	NO						
<a href="#">CB5349-000</a>	NO						
<a href="#">CB5362-000</a>	NO						
<a href="#">CB5364-000</a>	NO						
<a href="#">CB5368-000</a>	NO						
<a href="#">CB5370-000</a>	NO						
<a href="#">CB5377-000</a>	NO						
<a href="#">CB5378-000</a>	NO						
<a href="#">CB5383-000</a>	NO						
<a href="#">CB5429-000</a>	NO			"XFFR-03X25"			
<a href="#">CB5430-000</a>	NO			"XFFR-03X4", "5-1899230-5"			
<a href="#">CB5432-000</a>	NO			"XFFR-04X4", "5-1899230-7"			
<a href="#">CB5435-000</a>	NO			"XFFR-07X4", "1899235-9"			
<a href="#">CB5437-000</a>	NO			"XFFR-11X4", "5-1899230-8"			
<a href="#">CB5440-000</a>	NO			"XFFR-15X4", "6-1899230-0"			
<a href="#">CF3962-000</a>	NO						
<a href="#">CF6053-000</a>	NO						
<a href="#">CL0858-000</a>	NO			"SST-48-03/FR/97"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number (s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">CB5052-000</a>	NO			"6-1899211-8", "BSTS-17X4"			
<a href="#">CB5330-000</a>	NO						
<a href="#">CB5432-000</a>	NO			"XFFR-04X4", "5-1899230-7"			
<a href="#">CB5435-000</a>	NO			"XFFR-07X4", "1899235-9"			
<a href="#">CB5437-000</a>	NO			"XFFR-11X4", "5-1899230-8"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number (s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">CB5440-000</a>	NO			"XFFR-15X4", "6-1899230-0"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number (s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">CB5004-000</a>	NO			"BSTS-04X4", "3-1899225-1"			
<a href="#">CB5005-000</a>	NO						
<a href="#">CB5015-000</a>	NO			"1899279-5", "BSTS-07X4"			
<a href="#">CB5018-000</a>	NO			"BSTS-07X4FR"			
<a href="#">CB5036-000</a>	NO						
<a href="#">CB5043-000</a>	NO			"BSTS-15X4", "3-1899213-5"			
<a href="#">CB5045-000</a>	NO						
<a href="#">CB5060-000</a>	NO						
<a href="#">CB5062-000</a>	NO						
<a href="#">CB5309-000</a>	NO						
<a href="#">CB5346-000</a>	NO						
<a href="#">CB5349-000</a>	NO						
<a href="#">CB5362-000</a>	NO						
<a href="#">CB5364-000</a>	NO						
<a href="#">CB5368-000</a>	NO						
<a href="#">CB5370-000</a>	NO						
<a href="#">CB5377-000</a>	NO						
<a href="#">CB5378-000</a>	NO						
<a href="#">CB5383-000</a>	NO						
<a href="#">CB5430-000</a>	NO			"XFFR-03X4", "5-1899230-5"			
<a href="#">CB5432-000</a>	NO			"XFFR-04X4", "5-1899230-7"			
<a href="#">CB5435-000</a>	NO			"XFFR-07X4", "1899235-9"			
<a href="#">CB5437-000</a>	NO			"XFFR-11X4", "5-1899230-8"			
	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number (s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">CB5440-000</a>				"XFFR-15X4", "6-1899230-0"			
<a href="#">CF3962-000</a>	NO						
<a href="#">CF6053-000</a>	NO						
<a href="#">CL0858-000</a>	NO			"SST-48-03/FR/97"			