

PRODUCT CHANGE NOTIFICATION

Product Category CABLE MANAGERS 20210607-1

Product Group ROAR

ISSUE DATE: 14-Jun-21

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

Removal of M6 mounting screws from NetManager High Capacity horizontal cable manager products. Change will take place in production on July 2, 2021. Panduit will continue to include #12-24 mounting screws with affected part numbers.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*			

IMPACTED PART NUMBER(s)

- NM1
- NM2
- NM3
- NM4
- NM1WH
- NM2WH
- NM3WH
- NM4WH
- NMF1
- NMF2
- NMF3
- NMF4
- NMF1WH
- NMF2WH
- NMF3WH
- NMF4WH