

Part Change Notification Number:
TGEANA_PCN_0076sales@tglobaltechnology.com

t: +44 (0)1455 553 510

Date: 5th September 2022**Parts Affected:** GT20

<u>Old Manufacturer Part Number</u>	<u>Old Digikey Part Number</u>	<u>Replacement Manufacturer Part Number</u>	<u>Replacement Digikey Part Number</u>
GT20-100-100-0.23-0	GT20-100-100-0.23-0-ND	GT20-100-100-0.3-0	1168-GT20-100-100-0.3-0-ND
GT20-30-25-0.23-0	1168-GT20-30-25-0.23-0-ND	GT20-30-25-0.3-0	1168-GT20-30-25-0.3-0-ND
GT20-300-300-0.23-0	GT20-300-300-0.23-0-ND	GT20-320-320-0.3-0	1168-GT20-320-320-0.3-0-ND
GT20-150-150-0.23-0	1168-1945-ND	GT20-150-150-0.3-0	1168-GT20-150-150-0.3-0-ND
GT20-320-320-0.23-0	1168-1946-ND	GT20-320-320-0.3-0	1168-GT20-320-320-0.3-0-ND

Description: GT20 0.23mm thickness is now obsolete. The recommended replacement is the 0.3mm variant of the material.

Should you require more details or wish to discuss this please do not hesitate to contact us at sales@tglobaltechnology.com.

Last Buy: Effective Immediately**Approved By:** Duncan Bell, General Manager