



## Product Discontinuance Notice - PDN 16\_0021 Rev. -

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a product discontinuance for certain ADI products (see Discontinued Parts Material List below). Any issues with this PDN must be sent to ADI as soon as possible. The information contained within this PDN is considered proprietary and should not be shared outside of your company. ADI contact information is listed below.

**PDN Title:**

ADIS16300 and ADIS16305 Product Obsolescence

**Publication Date:** 04-Apr-2016

**Last Time Buy Date:** 30-Sep-2016

**Last Time Ship Date:** 31-Mar-2017

**Revision Description:**

Initial Release

**Reason For Discontinuance**

Limited raw material availability to continue production.  
Suggested replacement is the ADIS16460AMLZ.

**Supporting Documents**      None

**For questions on this PDN, send email to the regional contacts below or contact your local ADI sales representative**

**Americas:**    PDN\_Americas@analog.com

**Europe:**     PDN\_Europe@analog.com

**Japan:**        PDN\_Japan@analog.com

**Rest of Asia:** PDN\_ROA@analog.com

### PDN 16\_0021 Discontinued Parts Material List

Model	Product Family	Replacement Part	Pin To Pin Compatible	Comments
ADIS16300/PCBZ	ADIS16300	NONE	N/A	
ADIS16300AMLZ	ADIS16300	ADIS16460AMLZ	No	
ADIS16300FLEXZ	ADIS16300	NONE	N/A	
ADIS16305/PCBZ	ADIS16305	NONE	N/A	
ADIS16305AMLZ	ADIS16305	ADIS16460AMLZ	No	
ADIS1630X/FLEX	ADIS16305	NONE	N/A	

**Appendix A - PDN 16\_0021 Revision History**

<b>Rev</b>	<b>Publish Date</b>	<b>Rev Description</b>
Rev. -	04-Apr-2016	Initial Release

Analog Devices, Inc. Proprietary Information

DocId:1030 Layout Rev:2 Parent DocId:None