



NOTIFICATION OF OBSOLESCENCE

OPF512 FIBER OPTIC RECEIVER

OPTEK Technology
1645 Wallace Drive
Carrollton, TX 75006 USA

Phone: 972-323-2200
Facsimile: 972-323-2396
Email: sensors@optekinc.com
Website: www.optekinc.com

January 2, 2013

TT electronics Optoelectronics Business Unit (OPTEK Technology) announces the obsolescence of its OPF512 Fiber Optic Receiver

Effective Date of Obsolescence: 01/02/2013

Last Time Buy: No last time buy will be available for the OPF512

Recommended Replacement: No recommended replacement exists for the OPF512.

Factory Backlog: No factory backlog exists for OPF512.

Inventory: The most recent inventory reports show no distributor inventory for the OPF512.

TT electronics/Optek Technology regrets any inconvenience this obsolescence may cause your customers.

Sincerely,

A handwritten signature in black ink, appearing to be 'J. B. H.', written over a horizontal line.

Product Marketing Specialist
TT electronics/Optek Technology