



Product Name:	HPL 558/559	
	METRAL	
Product Manager:	Jibu Babu	
Subject:	Notification of Planned Change	
Distribution:	Affected customers	
Type of Change:	Packaging Change	
Change Description:	<p>Carrier Tape Packing Reel design change & colour change</p> <div style="display: flex; justify-content: space-around;"> <div style="border: 1px solid black; padding: 5px;"> <p style="color: red; margin: 0;">Before Change</p> <p>Existing Bobbin 2 parts (Flange 1 + Flange 2) Black Color</p>   </div> <div style="border: 1px solid black; padding: 5px;"> <p style="color: green; margin: 0;">After Change</p> <p>New Bobbin 3 parts (Flange 1 + Extender + Flange 2) Blue Color</p>   </div> </div> <p style="font-size: small; margin-top: 5px;">Description of Change. > Carrier Tape Packing Reel design change & colour change</p>	
Reason for Change:	Alternate supplier introduction for supply continuity. We will have the flexibility to choose colours "White, Black, Blue etc for Bobbins as available in the resin market due to disrupted supply chain.	
Affected Parts:	See Affected parts.xls	
Effective Date of Change:	30 June ,2022	
Last Time Buy Date:		
Earliest Disty Return Date:		
Last Time Shipment Date		
Datasheet Attached?	NA	
Qual/Test Data Attached?	NA	
Samples Availability Date:	28 June ,2022	
Available Alternatives?		
Questions?	Contact your local Amphenol Representative, or Product Manager	
	Jibu Babu / Product Manager	
	JIBU.BABU@FCI.COM	

Note:

Customers should contact Product Manager (or their local Amphenol Representative) directly regarding any concern on the PCN. Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .

MPN

- 10082662-102LF
- 10082662-202LF
- 10126372-102LF
- 10126372-202LF
- 10146708-101LF
- 58360-101LF
- 58360-102LF
- 58360-103LF
- 58361-101BKLF
- 58361-101LF
- 58361-201LF