



Harwin plc
Fitzherbert Road
Farlington, Portsmouth
Hampshire PO6 1RT
United Kingdom

Reception: +44 (0)23 9231 4545
Sales Desk: +44 (0)23 9237 0451
Fax: +44 (0)23 9231 4590

Monday 10th March, 2014

Dear Customer,

Re: Obsolescence notification for Harwin product.

Please be advised that a range of Datamate single items are now obsolete with immediate effect. Attached is the list of affected items in Excel Spreadsheet format: "Obsolescence notification spreadsheet - Datamate selection March 2014.xlsx".

Please consult this spreadsheet for the complete list of affected items. Alternative items are available; please see the attached spreadsheet for the alternative part numbers.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Management Team
technical@harwin.com

Obsolete Product Notification from Harwin

Part number being made obsolete	Alternative product	Drawing for alternative product
M80-4010601	M80-4010642	http://www.harwin.com/include/downloads/drawings/M80-401.PDF
M80-4012001	M80-4012042	http://www.harwin.com/include/downloads/drawings/M80-401.PDF
M80-4020601	M80-4020642	http://www.harwin.com/include/downloads/drawings/M80-402.PDF
M80-4021001	M80-4021042	http://www.harwin.com/include/downloads/drawings/M80-402.PDF
M80-4021201	M80-4021242	http://www.harwin.com/include/downloads/drawings/M80-402.PDF
M80-4022001	M80-4022042	http://www.harwin.com/include/downloads/drawings/M80-402.PDF
M80-4024201	M80-4024242	http://www.harwin.com/include/downloads/drawings/M80-402.PDF
M80-4050642	M80-4050605	http://www.harwin.com/include/downloads/drawings/M80-405.PDF
M80-4052001	M80-4052042	http://www.harwin.com/include/downloads/drawings/M80-405.PDF
M80-4054242	M80-4054205	http://www.harwin.com/include/downloads/drawings/M80-405.PDF
M80-4055042	M80-4055005	http://www.harwin.com/include/downloads/drawings/M80-405.PDF
M80-4060605	M80-4060642	http://www.harwin.com/include/downloads/drawings/M80-406.PDF
M80-4061042	M80-4061005	http://www.harwin.com/include/downloads/drawings/M80-406.PDF
M80-4063401	M80-4063442	http://www.harwin.com/include/downloads/drawings/M80-406.PDF
M80-4101001	M80-4101042	http://www.harwin.com/include/downloads/drawings/M80-410.PDF
M80-4101201	M80-4101242	http://www.harwin.com/include/downloads/drawings/M80-410.PDF
M80-4120601	M80-4120642	http://www.harwin.com/include/downloads/drawings/M80-412.PDF
M80-4121001	M80-4121042	http://www.harwin.com/include/downloads/drawings/M80-412.PDF
M80-4121201	M80-4021242	http://www.harwin.com/include/downloads/drawings/M80-402.PDF
M80-4121242	M80-4021242	http://www.harwin.com/include/downloads/drawings/M80-402.PDF
M80-4122001	M80-4122042	http://www.harwin.com/include/downloads/drawings/M80-412.PDF
M80-4211042	M80-4211005	http://www.harwin.com/include/downloads/drawings/M80-421.PDF
M80-4581098	M80-4551098	http://www.harwin.com/include/downloads/drawings/M80-455.PDF
M80-4581498	M80-4551498	http://www.harwin.com/include/downloads/drawings/M80-455.PDF
M80-4630605	M80-4630642	http://www.harwin.com/include/downloads/drawings/M80-463.PDF
M80-4651205	M80-4851205	http://www.harwin.com/include/downloads/drawings/M80-485.PDF
M80-4662042	M80-4662005	http://www.harwin.com/include/downloads/drawings/M80-466.PDF
M80-4712005	M80-4712042	http://www.harwin.com/include/downloads/drawings/M80-471.PDF
M80-4761005	M80-4661005	http://www.harwin.com/include/downloads/drawings/M80-466.PDF
M80-4851405	M80-4651405	http://www.harwin.com/include/downloads/drawings/M80-466.PDF
M80-5111442	M80-5111422	http://www.harwin.com/include/downloads/drawings/M80-511.PDF
M80-5120622	M80-5120642	http://www.harwin.com/include/downloads/drawings/M80-512.PDF
M80-5121022P	M80-5121042P	http://www.harwin.com/include/downloads/drawings/M80-512P.PDF
M80-5121222	M80-5121242	http://www.harwin.com/include/downloads/drawings/M80-512.PDF

Obsolete Product Notification from Harwin

Part number being made obsolete	Alternative product	Drawing for alternative product
M80-5122022P	M80-5122042P	http://www.harwin.com/include/downloads/drawings/M80-512P.PDF
M80-5200622	M80-5200642	http://www.harwin.com/include/downloads/drawings/M80-520.PDF
M80-5201222	M80-5201242	http://www.harwin.com/include/downloads/drawings/M80-520.PDF
M80-5202022	M80-5202042	http://www.harwin.com/include/downloads/drawings/M80-520.PDF
M80-5203442	M80-5203422	http://www.harwin.com/include/downloads/drawings/M80-520.PDF
M80-5212022	M80-5212042	http://www.harwin.com/include/downloads/drawings/M80-521.PDF
M80-5213422	M80-5213442	http://www.harwin.com/include/downloads/drawings/M80-521.PDF
M80-5220622	M80-5220642	http://www.harwin.com/include/downloads/drawings/M80-522.PDF
M80-5221042	M80-5221005	http://www.harwin.com/include/downloads/drawings/M80-522.PDF
M80-5221222	M80-5221242	http://www.harwin.com/include/downloads/drawings/M80-522.PDF
M80-5222022	M80-5222042	http://www.harwin.com/include/downloads/drawings/M80-522.PDF
M80-5223422	M80-5223442	http://www.harwin.com/include/downloads/drawings/M80-522.PDF
M80-5224242	M80-5224222	http://www.harwin.com/include/downloads/drawings/M80-522.PDF
M80-5304222	M80-5304242	http://www.harwin.com/include/downloads/drawings/M80-530.PDF
M80-5314242	M80-5314222	http://www.harwin.com/include/downloads/drawings/M80-531.PDF
M80-5321022	M80-5321042	http://www.harwin.com/include/downloads/drawings/M80-532.PDF
M80-5321222	M80-5321242	http://www.harwin.com/include/downloads/drawings/M80-532.PDF
M80-5322022	M80-5322042	http://www.harwin.com/include/downloads/drawings/M80-532.PDF
M80-5413422	M80-5413442	http://www.harwin.com/include/downloads/drawings/M80-541.PDF
M80-5421222	M80-5421242	http://www.harwin.com/include/downloads/drawings/M80-542.PDF
M80-5421422	M80-5421442	http://www.harwin.com/include/downloads/drawings/M80-542.PDF
M80-5431842	M80-5431805	http://www.harwin.com/include/downloads/drawings/M80-543.PDF
M80-5432642	M80-5432605	http://www.harwin.com/include/downloads/drawings/M80-543.PDF
M80-5500842	M80-5300842	http://www.harwin.com/include/downloads/drawings/M80-530.PDF
M80-5501222	M80-5501242	http://www.harwin.com/include/downloads/drawings/M80-550.PDF
M80-5502042	M80-5502005	http://www.harwin.com/include/downloads/drawings/M80-550.PDF
M80-5511022	M80-5511042	http://www.harwin.com/include/downloads/drawings/M80-551.PDF
M80-5520622	M80-5520642	http://www.harwin.com/include/downloads/drawings/M80-552.PDF
M80-5521022	M80-5521005	http://www.harwin.com/include/downloads/drawings/M80-552.PDF
M80-5521042	M80-5521005	http://www.harwin.com/include/downloads/drawings/M80-552.PDF
M80-5521222	M80-5521242	http://www.harwin.com/include/downloads/drawings/M80-552.PDF
M80-5522022	M80-5522042	http://www.harwin.com/include/downloads/drawings/M80-552.PDF
M80-5634205	M80-5624205	http://www.harwin.com/include/downloads/drawings/M80-562.PDF
M80-5652005	M80-5602005	http://www.harwin.com/include/downloads/drawings/M80-560.PDF

Obsolete Product Notification from Harwin

Part number being made obsolete	Alternative product	Drawing for alternative product
M80-5700605	M80-5600605	http://www.harwin.com/include/downloads/drawings/M80-560.PDF
M80-5701405	M80-5601405	http://www.harwin.com/include/downloads/drawings/M80-560.PDF
M80-5702605	M80-5602605	http://www.harwin.com/include/downloads/drawings/M80-560.PDF
M80-5703405	M80-5603405	http://www.harwin.com/include/downloads/drawings/M80-560.PDF
M80-5704205	M80-5604205	http://www.harwin.com/include/downloads/drawings/M80-560.PDF
M80-5705005	M80-5605005	http://www.harwin.com/include/downloads/drawings/M80-560.PDF
M80-5711405	M80-5611405	http://www.harwin.com/include/downloads/drawings/M80-561.PDF
M80-5713405	M80-5613405	http://www.harwin.com/include/downloads/drawings/M80-561.PDF
M80-5714205	M80-5614205	http://www.harwin.com/include/downloads/drawings/M80-561.PDF
M80-5761005	M80-5661005	http://www.harwin.com/include/downloads/drawings/M80-566.PDF
M80-5821005	M80-5621005	http://www.harwin.com/include/downloads/drawings/M80-562.PDF
M80-5824205	M80-5624205	http://www.harwin.com/include/downloads/drawings/M80-562.PDF
M80-5834205	M80-5624205	http://www.harwin.com/include/downloads/drawings/M80-562.PDF
M80-6130442	M80-8890405	http://www.harwin.com/include/downloads/drawings/M80-889.PDF
M80-6130642	M80-8890605	http://www.harwin.com/include/downloads/drawings/M80-889.PDF
M80-6133445	M80-8893405	http://www.harwin.com/include/downloads/drawings/M80-889.PDF
M80-6140245	M80-6140242	http://www.harwin.com/include/downloads/drawings/M80-614.PDF
M80-6140345	M80-6140342	http://www.harwin.com/include/downloads/drawings/M80-614.PDF
M80-6152042	M80-6152045	http://www.harwin.com/include/downloads/drawings/M80-615.PDF
M80-6160422	M80-6160442	http://www.harwin.com/include/downloads/drawings/M80-616.PDF
M80-6160842	M80-6160822	http://www.harwin.com/include/downloads/drawings/M80-616.PDF
M80-6650422	M80-6650442	http://www.harwin.com/include/downloads/drawings/M80-665.PDF
M80-6650622	M80-6650642	http://www.harwin.com/include/downloads/drawings/M80-665.PDF
M80-6650822	M80-6650842	http://www.harwin.com/include/downloads/drawings/M80-665.PDF
M80-6651022	M80-6651042	http://www.harwin.com/include/downloads/drawings/M80-665.PDF
M80-6651222	M80-6651242	http://www.harwin.com/include/downloads/drawings/M80-665.PDF
M80-6670422	M80-6670442	http://www.harwin.com/include/downloads/drawings/M80-667.PDF
M80-6670622	M80-6670642	http://www.harwin.com/include/downloads/drawings/M80-667.PDF
M80-6670822	M80-6670842	http://www.harwin.com/include/downloads/drawings/M80-667.PDF
M80-6671022	M80-6671042	http://www.harwin.com/include/downloads/drawings/M80-667.PDF
M80-6671222	M80-6671242	http://www.harwin.com/include/downloads/drawings/M80-667.PDF
M80-6810401	M80-6810442	http://www.harwin.com/include/downloads/drawings/M80-681.PDF
M80-6810445	M80-6810442	http://www.harwin.com/include/downloads/drawings/M80-681.PDF
M80-6810801	M80-6810842	http://www.harwin.com/include/downloads/drawings/M80-681.PDF

Obsolete Product Notification from Harwin

Part number being made obsolete	Alternative product	Drawing for alternative product
M80-6811001	M80-6811042	http://www.harwin.com/include/downloads/drawings/M80-681.PDF
M80-6811201	M80-6811242	http://www.harwin.com/include/downloads/drawings/M80-681.PDF
M80-6811601	M80-6811642	http://www.harwin.com/include/downloads/drawings/M80-681.PDF
M80-6813442	M80-6813445	http://www.harwin.com/include/downloads/drawings/M80-681.PDF
M80-7015122	M80-7015142	http://www.harwin.com/include/downloads/drawings/M80-701.PDF
M80-7062705	M80-7052705	http://www.harwin.com/include/downloads/drawings/M80-705.PDF
M80-7092705	M80-7082705	http://www.harwin.com/include/downloads/drawings/M80-708.PDF
M80-7096305	M80-7086305	http://www.harwin.com/include/downloads/drawings/M80-708.PDF
M80-7101542	M80-7101522	http://www.harwin.com/include/downloads/drawings/M80-710.PDF
M80-7520222	M80-7520242	http://www.harwin.com/include/downloads/drawings/M80-752.PDF
M80-7520342	M80-7520322	http://www.harwin.com/include/downloads/drawings/M80-752.PDF
M80-7520442	M80-7520422	http://www.harwin.com/include/downloads/drawings/M80-752.PDF
M80-7540642	M80-7540622	http://www.harwin.com/include/downloads/drawings/M80-754.PDF
M80-7541442	M80-7541422	http://www.harwin.com/include/downloads/drawings/M80-754.PDF
M80-7700442	M80-7700445	http://www.harwin.com/include/downloads/drawings/M80-770.PDF
M80-7700642	M80-7700645	http://www.harwin.com/include/downloads/drawings/M80-770.PDF
M80-7703442	M80-8503442	http://www.harwin.com/include/downloads/drawings/M80-850.PDF
M80-7703445	M80-8503445	http://www.harwin.com/include/downloads/drawings/M80-850.PDF
M80-8100405	M80-8160405	http://www.harwin.com/include/downloads/drawings/M80-816.PDF
M80-8110405	M80-8170405	http://www.harwin.com/include/downloads/drawings/M80-817.PDF
M80-8111005	M80-8121005	http://www.harwin.com/include/downloads/drawings/M80-812.PDF
M80-8141822	M80-8391842	http://www.harwin.com/include/downloads/drawings/M80-839.PDF
M80-8170805	M80-8130805	http://www.harwin.com/include/downloads/drawings/M80-813.PDF
M80-8171005	M80-8131005	http://www.harwin.com/include/downloads/drawings/M80-813.PDF
M80-8260422	M80-8260442	http://www.harwin.com/include/downloads/drawings/M80-826.PDF
M80-8270422	M80-8270442	http://www.harwin.com/include/downloads/drawings/M80-827.PDF
M80-8271622	M80-8271642	http://www.harwin.com/include/downloads/drawings/M80-827.PDF
M80-8271822	M80-8271842	http://www.harwin.com/include/downloads/drawings/M80-827.PDF
M80-8272622	M80-8272642	http://www.harwin.com/include/downloads/drawings/M80-827.PDF
M80-8273422	M80-8273442	http://www.harwin.com/include/downloads/drawings/M80-827.PDF
M80-8284422	M80-8284442	http://www.harwin.com/include/downloads/drawings/M80-828.PDF
M80-8350422	M80-8360442	http://www.harwin.com/include/downloads/drawings/M80-836.PDF
M80-8370642	M80-8360642	http://www.harwin.com/include/downloads/drawings/M80-836.PDF
M80-8450345	M80-8980305	http://www.harwin.com/include/downloads/drawings/M80-898.PDF

Obsolete Product Notification from Harwin

Part number being made obsolete	Alternative product	Drawing for alternative product
M80-8504445	M80-8504442	http://www.harwin.com/include/downloads/drawings/M80-850.PDF
M80-8552022	M80-6172042	http://www.harwin.com/include/downloads/drawings/M80-617.PDF
M80-8581022	M80-8251042	http://www.harwin.com/include/downloads/drawings/M80-825.PDF
M80-8760705	M80-8760722	http://www.harwin.com/include/downloads/drawings/M80-876.PDF
M80-8780322	M80-8430342	http://www.harwin.com/include/downloads/drawings/M80-843.PDF
M80-8780522	M80-8430542	http://www.harwin.com/include/downloads/drawings/M80-843.PDF
M80-8810345	M80-8810342	http://www.harwin.com/include/downloads/drawings/M80-881.PDF
M80-8910805	M80-6150845	http://www.harwin.com/include/downloads/drawings/M80-615.PDF
M80-9401042	M80-9401005	http://www.harwin.com/include/downloads/drawings/M80-940.PDF
M80-9402642	M80-9402605	http://www.harwin.com/include/downloads/drawings/M80-940.PDF
M80-9431005	M80-9421005	http://www.harwin.com/include/downloads/drawings/M80-942.PDF
M80-9431205	M80-9421205	http://www.harwin.com/include/downloads/drawings/M80-942.PDF