

Part Change Notification Number:
 TGEANA_PCN_0070

sales@tglobaltechnology.com

t: +44 (0)1455 553 510

Date: 19th April 2022

Parts Affected: TG-PP10/S606P

Old Manufacturer Part Number	Old Digikey Part Number	New Manufacturer Part Number	New Digikey Part Number
S606P-30	1168-S606P-30-ND	TG-S808-30	1168-TG-S808-30-ND
S606P-50	1168-S606P-50-ND	TG-S808-30	1168-TG-S808-30-ND
S606P-500	1168-S606P-500-ND	TG-S808-1000	1168-TG-S808-1000-ND
S606P-1000	1168-S606P-1000-ND	TG-S808-1000	1168-TG-S808-1000-ND
TG-PP10-30	1168-TG-PP10-30-ND	TG-A7000-55CC	1168-TG-A7000-55CC-ND
TG-PP10-50	1168-TG-PP10-50-ND	TG-A7000-55CC	1168-TG-A7000-55CC-ND
TG-PP10-500	1168-TG-PP10-500-ND	TG-A7000-1000	1168-TG-A7000-1000-ND
TG-PP10-1000	1168-TG-PP10-1000-ND	TG-A7000-1000	1168-TG-A7000-1000-ND

Reason: Low Demand

Description: Due to the low demand for the product TG-PP10 and S606P Series, T-Global have taken the decision to obsolete this material from their portfolio. For any further questions about the replacement material, please contact sales@tglobaltechnology.com.

Last Buy: 31/10/2022



Approved By: Duncan Bell, General Manager