


Product Change Notification (PCN)

PCN Number	501667	Date Issued	November 07, 2016
Reason for Change	Obsolete		
Change Type Description	This is to inform you that the part(s) referenced in this notice will be made obsolete due to low demand. Please contact your Molex Sales Engineer for additional questions concerning possible replacement part(s).		
Planned Implementation Date	September 02, 2017		
Last Time Buy Date for Obsolete Parts	June 02, 2017		
Last Time Ship Date for Obsolete Parts	September 02, 2017		

Before Change

MX150 2x4 Receptacle



Molex Confidential Information
© 2016 Molex - All Rights Reserved. Unauthorized Reproduction Prohibited. MOLEX CONFIDENTIAL

After Change

MX150 2x4 Ring Seal Overview

- **Changing from LIM technology to HCR technology**
 - Current tool is reaching end of life and needs replacement
 - Additional mold required for capacity
 - Moving manufacturing location from US to CN to better align with Molex manufacturing plant
 - Inline with other MX150 Receptacle Ring Seals
- **Product Impact**
 - Ring Seal Material Change
 - Ring Seal Geometry Change
 - Inline with other MX150 Receptacle Ring Seals
 - Color change from Green to Rust Red
- **Assembly Part Number Impact**
 - Molex P/Ns 33472-08xx, 33472-09xx, 33472-10xx will be obsolete, replaced by 33472-48xx, 33472-49xx, 33472-50xx
 - Suffix change only



molex

Molex Confidential Information
© 2016 Molex - All Rights Reserved. Unauthorized Reproduction Prohibited. MOLEX CONFIDENTIAL

molex



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:501667**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL: 630-969-4747
www.molex.com

Molex Part #

334720802

334720806

334720807

334720901